

TOWNSHIP 25 RANGE 01E POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION N 1/4 Cor. Sec. 2 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Joseph A Ganong & John G Collins, US Cadastral Engineers under instructions dated March 12, 1921, surveyed May 1927/June 1928 - (DCSO Records Vol. 21 Page(s) 9128)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor. of sec. 2 only, with brass cap marked

1/4 S S2
1928

from which

- A fir, 10" dia., bears S.45°E., 38 lks., mkd: 1/4 S2 BT.
- A fir, 8" dia., bears S.26°W., 22 lks., mkd: 1/4 S2 BT.

Dennis Gaylord, LS 1636, USFS & DCSO Deputy - Witness: Bill West - April 19, 1979 - C.S. file 60/24-36

Found - 1" Iron pipe with a 1928 GLO brass cap attached properly marked. Pipe is set loosely in ground.
A 12" D.Fir bears S.26°W., 14.52 ft. Has a single healed blaze.

A 17" D.Fir bears S.45°E., 25.08 ft. This tree is still living but all signs of a blaze have been destroyed by logging activities.

Set - I place a mound of stone around the iron pipe.

New BT- An 18" D.Fir bears S.70°30'E., 35.4 ft. scribed "1/4 S2 BT" on double blazes.

Note - Corner 1/4 S35 T24S, R1E, bears East, 65.97 ft. (Rec. N.88°14'E., 96 lks. or 63.36 ft.)

USFS BT signs were placed on all BTs.

This corner is about 50 ft. north of FS Rd. #2512.