

PRIMARY CORNER DESCRIPTION South Cor. Secs. 35 & 36 only; T24-1E

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Alonso Gesner, Deputy Surveyor, under contract No. 659, dated May 21, 1896 - (DCSO records Vol. 21 Pg 9104)

Set basalt stone, 12x10x5", 7" in the ground on side hill, sloping N for cor. to secs. 1, 2, 35, & 36, marked with 5 notches on the West and 1 notch on the E sides, from which
A fir, 10" dia., bears N.46°40'E., 25 lks., mkd: T24S R1E S36 BT.
A fir, 10" dia., bears S.54°30'E., 30 lks., mkd: T25S R1E S1 BT.
A fir, 10" dia., bears S.79°W., 59 lks., mkd: T25S R1E S2 BT.
A fir, 20" dia., bears N.22°30'W., 110 lks., mkd: T24S R1E S35 BT.

GLO survey by Joseph A Ganong & John G Collins, US Cadastral Engineers under instructions dated March 12, 1921, surveyed May 1927/June 1928 - (DCSO Records Vol. 21 Page(s) 9126)

The cor. established for secs. 1, 2, 35 & 36, which is a basalt stone, 6x10x6" above ground, firmly set, marked with 5 notches on W and 1 notch on E. edges; from which
A fir, 30" dia., bears N.22½°W., 110 lks. mkd T24S R1E S35 BT. (Old B.T.)
The remaining bearing trees have been burned.
I now change this cor. to refer to secs. 35 and 36 only.
Re-mark the stone
S 36 on NE., and
S 35 on NW. face; from which.
A fir, 8" dia., bears N.73½°E., 163 lks., mkd T24S R1E S36 BT. (New B.T.)

Dennis Gaylord, LS 1636, USFS & DCSO Deputy - Witness: Bill West - April 19, 1979 - C.S. file 60/24-40

Found - Original corner stone was found loosely set in the ground. The stone, which measures 14x9x5" is marked with 5 grooves on the west face and one groove on the east face. No other marks discernible.
A 38" D.Fir bears N.23°30'W., 72.6 ft. & has a nearly healed single blaze which has been previously opened.
A 24" D.Fir bears N.74°E., 107.58 ft. & has a healed single blaze. This tree has been badly damaged by rock fall.
Nothing remains of the other BTs of record.
continued next page

TOWNSHIP 25 RANGE 01E POINT IDENTIFIER # 601700

PRIMARY CORNER DESCRIPTION South Cor. Secs. 35 & 36 only; T24-1E

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set - Moving the corner stone aside, I set in its place a 1½x6" iron pipe with a 2½" brass cap attached
Brass cap marked: T24S R1E S35 S36 S1 T25S R1E
PLS 1636 1979. I bury the corner stone alongside.
New BT - A 15" D.Fir bears N.25°30'W., 56.8 ft. scribed T24S
R1E S36 BT" on a double blaze.
Note - Compass declination: 18°E.
Corner S1 S2 (T25S-R1E) bears S.89°30'W.) 57.3 ft. (Rec
S.89°02'W., 0.86 chs. (56.76 ft.))
Corner lies approx. 75 ft. north of FS Rd. No. 2512. USFS
bearing tree signs were placed on all BTs.

Lane Co. Surveyors Office - D. Michael Jackson - By: Bruce
Bothel, Associate Surveyor & John Randall, Engineering Tech
1 - Sept. 17, 2007 - C.S. File 65/76-43

Found - A 2½" brass cap dated 1979 atop a 1" IP in stone
mound.
A 43" D.Fir with healed face brs N.23°36'W., 71.8'
(N.22°30'W., 72.6') 1898
A 24"x30" tall rotten D.Fir snag with healed face
brs N.73°07'E., 106.8' (N.73°E., 107.6') 1928
A 2½" brass cap dated 1928 (25-15-01 NW CC) brs
S.89°12'20"W., 57.42' (S.89°02'W., 56.8') 1928
A 22" D.Fir with healed face brs N.25°00'E., 56.3'
(N.25°30'E., 56.8') 1979
Set - 2" alum cap "LCSO-RP1-2007" atop a 5/8x30" rebar brs
S.11°04'W., 22.49'
Geographic Map Location (NAD 83/91 Values) - Use for
navigating to corner area - not of survey grade
accuracy. Lat: 43°26'17.4" Long: 122°38'31.9"