

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3562)

Set a hemlock post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor., mkd. 1/4 S18 on N & S19 on S faces, from which
A hemlock, 7" dia., bears N.7 1/2°E., 34 lks., mkd: 1/4 S18 BT.
A chinquapin, 4" dia. bears S.15°E., 20 lks. mkd: 1/4 S19 BT

Reported as not fd by V.R. Tracy May 1967, C.S. 52/30-78A

BLM Dependent resurvey by James E. Jelley, Cadastral Surveyor under Group #350 & 929 surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16353)

Point for the 1/4 sec. cor. of secs. 18 & 19, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2 1/2" dia., 24" in the ground with brass cap marked:
T25S R1W
1/4 S 18
S 19
1978
from which
A fir, 5" dia., bears N.50 1/2°E., 15 lks., mkd: 1/4 S18 BT.
A fir, 5" dia., bears S.32 3/4°E., 9 1/2 lks., mkd: 1/4 S19 BT.

BLM resurvey by A. Bert Skeesick & Daniel E. Weller, Cadastral Surveyors under Group #1888, surveyed Sept. 1998/Sept. 1999 - (DCSO rec. Vol. 53 Page(s) 20703)

The 1/4 sec. cor. of secs. 18 & 19, monumented with an iron post, 2 1/2" dia., firmly set, projecting 2" above ground, with brass cap mkd.
T25S R1W
1/4 S 18
S 19
1978
from which bearing trees mkd. by Jelley
A fir, 10" dia. bears N.50 1/2°E., 15 lks. with healed blaze
A fir, 12" dia. bears S.32 3/4°E., 9 1/2 lks. with healed blaze