

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3565)

Set a basalt stone, 18x8x7", 12" in the ground for ¼ sec. cor. mkd ¼ on N face, from which

A dogwood, 5" dia., bears N.38°W., 20 lks., mkd: ¼ S7 BT.

A chinquapin, 4" dia. bears S.14°W., 15 lks. mkd: ¼ S18 BT

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor, under Group #353, Surveyed July/Aug. 1957 - (DCSO records Vol. 28 Page(s) 12140-1)

Point for the ¼ sec. cor. of secs. 7 & 18, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 36 long, 2" dia., 28" in the ground with brass cap marked:

T25S R1W

¼ S 7

 S 18

1957

from which

A fir, 30" dia., bears N.1°E., 39 lks., mkd: ¼ S7 BT.

A hemlock, 7" dia., bears S.39½°W., 133 lks. mkd: ¼ S18 BT

BLM resurvey by A. Bert Skeesick & Daniel E. Weller, Cadastral Surveyors under Group #1888, surveyed Sept. 1998/Sept. 1999 - (DCSO rec. Vol. 53 Page(s) 20700)

The ¼ sec. cor. of secs. 7 & 18, monumented with an iron post, 2" dia, firmly set, projecting 3" above ground, (with rotted wood post, 3 ft. long, 4" square, mkd. 1/4 COR lying alongside), with brass cap (properly) mkd.

from which the bearing trees mkd. by Roseberry

A fir, 44" dia, bears N.1¾°E., 37 lks., with a healed blaze. (Record, N.1°E., 39 lks.)

A hemlock, 14" dia, bears S.39½°W., 130 lks., with a healed blaze. (Record, 133 lks.)