

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32 only, (South)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Hezekiah H. Johnson, Deputy Surveyor, under Contract #721, dated May 1, 1900 - (DCSO records Vol. 8 Page(s) 3505)

-----  
Set a Fir post 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 5, 6, 31 and 32, marked T25S S32 on NE.; R1W S5 on SE.; T26S S6 on SW.; and S31 on NW. faces, from which  
A Fir 9" dia., bears N.72°E., 45 lks. dist.mkd. T25S R1W S32 BT.  
A Fir 9" dia., bears S.73½°E., 33 lks. dist. mkd. T26S R1W S5 BT.  
A Fir 11" dia., bears S.1°W., 29 lks. dist. mkd. T26S R1W S6 BT.  
A Fir 8" dia., bears N.69°W., 86 lks. dist. mkd. T25S R1W S31 BT.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #797, dated April 19, 1910 - (DCSO records Vol. 9 Page(s) 3576) and (duplicate Pages 4081-82, Vol. 10)

-----  
The cor. of secs. 5, 6, 31 and 32, which is a Fir post 4" sq., 12" above ground, firmly set, marked and witnessed as described by the surveyor general, except the NE. bearing tree, which cannot be found.  
I re-establish this cor. in its original position as the cor. of secs. 31 and 32, T25S R1W, only, as follows:  
Post above described, already set, from which  
A Fir 12" dia., bears N.84°E., 27 lks. dist. mkd. T25S R1W S32 BT.  
A Fir 10" dia., bears N.69°W., 86 lks. dist. mkd. T25S R1W S31 BT.  
I obliterate marks on bearing trees referring to T26S.