

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 20

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3559-60)</p> <p>-----</p> <p>Summit of spur, slopes W & set a cedar post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S19 on W & S20 on E faces, from which</p> <p> A cedar, 8" dia., bears N.85°E., 62 lks., mkd: 1/4 S20 BT.</p> <p> A fir, 12" dia., bears S.72°W., 4 lks., mkd: 1/4 S19 BT.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - May 1967 - C.S. File 52/30-80</p> <p>-----</p> <p>Found - Orig. 8", now 16" Cedar N.85°E., 40.9 ft. Alive, we open & find "1/4 S20" scribe.</p> <p> Orig. 12", now 30" fir, S.75°W. 2.6 ft., now lying nearly face down.</p> <p>Set - Brass Cap at Cor. mkd. County Surveyors T25S R1W Office, 1967 1/4 S19 S20</p> <p>New BTs- 16" cedar S.73°E., 38.8 ft. mkd. 1/4 S20 CS BT.</p> <p> 7" Chinquapin S.39°W., 56.2 ft. mkd. S19 CS BT.</p> <p> (Scribed 4' above ground due to log)</p> <p>Note - This corner lies in logged-off area on top of spur ridge sloping W.</p>
<p>Fd. & used on BLM Dependent resurvey by James E. Jelley, Cadastral Surveyor under Group #350 & 929 surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16360-1)</p>
<p>Tony Hostetter - For: Seneca Jones Timber Co. - April 2003 - M142-3</p> <p>-----</p> <p>Found - Brass cap and accessories as described by County Surveyor in 1967 (C.S. 52/30).</p> <p>New BTs- 12" Fir, scribed "S19 1/4 BT" bears; S.09°W., 67.4 ft. to spike.</p> <p> 18" hemlock, scribed S19 1/4 BT" bears; S.86°W., 18.3 ft to spike.</p>