

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 5; & 32, T24-1

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A 5" now 6" Hemlock, alive with scribing "¼ S5 CS BT" visible on unhealed double blaze, bears S.44½°E., 32.5 ft. (Rec. S.49°E., 32.5 ft.)
At a location which agrees with the measurements listed for the previously described corner accessories, WE RESET the 1966 DCSO brass cap 28" in the ground on a steep N. slope and add the markings "Reset 1978" to the brass cap.
New Accessories:
A boat spike marked "BT 1" set near the heart on top of a 54" S.Pine stump, bears S.87°W., 32.3 ft.
Corner is located in cut over area.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2500, Surveyed Sept./Nov. 2011 - (DCSO records BLM Plat T25-1W 2012-2 & Vol. 58 Pages 22945-6)

The ¼ sec. cor. of secs. 5 & 32, on the N bdy. of the Tp., perpetuated by the Douglas Co. Surveyor's Office 1966 & 1978, monumented with an iron post, 1¼" dia., firmly set, flush with the ground surface, with brass cap (properly) mkd from which the remains of the orig. BTs

A roothole bears S.74°E., 18.5 ft. downhill of which is an uprooted fir snag, 51" dia., with no marks visible on a partially healed blaze.

A decayed cedar stump, size indeterminate, bears N.43°W., 5.3 ft. with no marks visible on a partially healed blaze.

and the remains of a BT mkd by Douglas Co. Surveyor's Office in 1966

A split hemlock stump, size indeterminate, bears S.46°E., 32.6 ft. with scribe marks BT visible on an open blaze. and an accessory set by the Douglas Co. Surveyor's Office in 1978

An iron spike, 1/2" square, bears S.86½°W., 32.4 ft., driven flush with the top and near the center of a sawed sugar pine stump, 51" dia., with a convex head mkd. BO-1

and new BTs

A fir, 7" dia., bears S.27°E., 33.7 ft., mkd: ¼ S5 BT.

A hemlock, 11" dia., bears N.85¼°W., 21.7 ft mkd: ¼ S32 BT

Gerald V. Nygren - For: Barnes & Assoc. Inc. - 11/2016 - M172-62

Found - 1966 C.S. brass cap per rec.
(1896) 36" Fir, now root hole bears S.74°E., 18.5'
14" Cedar, now rotten stump bears N.43°W., 5.3', no marks visible. continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

(1966) 5" Hemlock, now split stump bears S.46°E., 32.6' healed face
(1978) 54" S.Pine stump, now 51" with 1/2" square iron spike in top near center bears S.86°30'W., 32.4'
(2011) 7" Fir, now 8" bears S.27°E., 33.7' visible scribe.
11" Hemlock, now 12" bears N.85°15'W., 21.7' visible scribe.

Russell Badgley - For: Seneca Jones Timber Co. - 3/2021 - M179-9

Found - A 1" iron post by Tracy, in 1966 & reset by Langlitz in 1978, firmly set & projecting 2" above the ground, with a 2½" brass cap (properly) marked, from which
A split stump hemlock (1966) bears (S.46°E., 32.6')2016 rec.
A 51" sugar pine stump (1978) with a 1/2" square iron spike in the top near center bear (S.86°30'W., 32 4')2016 rec
A 10" D.Fir (2011) bears S.27°15'E., 33.6 ft w/visible scribe (S.27°E., 33.7')2016 rec
A 14" Hemlock (2011) bears N.85°00'W., 21.7 ft w/visible scribe (N.85°15'W., 21.7 ft) 2016 rec
New BTs- A 15" D.Fir bears S.72°45'E., 36.4 ft scribed "¼ S5 BT" on double blaze
A 15" Hemlock bears N.42°40'W., 15.6 ft scribed "¼ S32 BT" on double blaze.