

PRIMARY CORNER DESCRIPTION Cor Secs 16, 17, 20, & 21

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3545-6)

Set a hemlock stake, 3 ft. long, 4" sq., 24" it the ground for. cor. of secs. 16, 17, 20 & 21 mkd T25S S16 on NE, R1W S21 on SE, S20 on SW & S17 on NW faces, with 3 notches on S & 4 notches on E edges, from which

A hemlock, 4" dia., bears N.31°E., 11 lks., mkd: T25S R1W S16 BT.

A cedar, 14" dia bears S.45°E. 75 lks mkd: T25S R1W S21 BT

A cedar, 18" dia bears S.55°W. 26 lks mkd: T25S R1W S20 BT

A cedar, 9" dia. bears N.52°W. 33 lks mkd: T25S R1W S17 BT

V.W. Hosford - For: Evans Products Co. - April 5th thru Nov. 25, 1960 - C.S. File 51/152 & M 20-2

At this point a thorough search failed to reveal any conclusive evidence of the original, corner. This area has burned at least twice since the orig. cor. was established & all that remains now are badly burned snags & windfalls. In the re-establishment of this corner, I gave the most weight to natural objects & to old blazes along the line between secs. 17 & 20. The four stream crossings noted in the first 20.75 chains west were much more than ordinarily accurate. By placing the corner from the calls on this line a burned cedar stub in the SE quad. & a cedar windfall in the SW quad. appear to be the remains of two orig. BTs.

At this point, which is in the previously mentioned tractor-built fire trail, I drove a 1½" iron pipe 36", long 12" above, the ground from which:

48" Fir bears S.59½°W. 49.0 ft. mkd. T25S S20 253 BT.

54" Fir bears N.11½°W. 130.5 ft. mkd. R1W S17 253 BT.

48" Fir Snag bears N.47¼°E. 68.1 ft. mkd: T25S S16 253 BT

No suitable tree in SE quadrant.

Fd. Ok by V. R. Tracy, DCSO - 5/1962, C.S. File 52/30-78A
FD. Ok by Ronald G. Geisler - 11/1984, C.S. File 58/146-13

BLM resurvey by A. Bert Skeesick & Daniel E. Weller, Cadastral Surveyor under Group #1888, surveyed Sept. 1998/Sept 1999- (DCSO rec. Vol. 53 Page(s) 20691-2)

The cor. of secs. 16, 17, 20, & 21, reestablished from orig topographic ties by Hosford, in 1960, & is accepted; monumented with an iron pipe, 1½" dia., firmly set, projecting 18" above ground, from which the remains of bearing trees mkd. by Hosford

continued next page

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Cor. Secs. 16, 17, 20, & 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A rotted fir stump, 22" dia., 3 ft. high, bears N.46¾°E., 103 lks., with rotted trunk lying alongside, with scribe marks 25S S16 BT visible on a partially healed blaze.

A fir snag, 44" dia., bears S.60¼°W., 76 lks., with scribe marks S21 BT visible on a partially healed blaze.

A fir snag, 46" dia., bears N.12°W., 200 lks., with scribe marks R W S17 25SBT visible on a partially healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 22" in the ground directly over the iron pipe, with brass cap mkd.

T25S	R1W
S 17	S 16
S 20	S 21
1999	

from which

A fir, 15" dia. bears N.73°E. 33 lks. mkd. T25S R1W S16 BT

A fir, 12" dia. bears S.12°E. 29 lks. mkd. T25S R1W S21 BT

A fir, 10" dia. bears S.67½°W. 37 lks mkd. T25S R1W S20 BT

No suitable accessories available in sec. 17.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Cor. is located at the end of the remains of an old tractor trail, 6 ft. wide, bears N.30°E.