

PRIMARY CORNER DESCRIPTION Cor Secs 8, 9, 16, & 17

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GL0 Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3547-8)

Set a basalt stone, 18x10x8" 12" in the ground for cor. of secs. 8, 9, 16, & 17, marked with 4 notches on S & E edges, from which

- A fir, 16" dia. bears N.30°E., 12 lks. mkd: T25S R1W S9 BT
- A cedar, 8" dia. bears S.59°E. 32 lks mkd: T25S R1W S16 BT
- A fir, 5" dia. bears S.14°W., 50 lks. mkd: T25S R1W S17 BT
- A fir, 6" dia., bears N.42°W., 21 lks. mkd: T25S R1W S8 BT

Bruce Shaner - For: National Plywood, Inc. - Wit. WM James, & James Griffin - April 21, 1960 - C.S. file 51/92-2

The orig, surveyor thoroughly fouled up his recorded notes by misnaming the BT species & by giving wrong bearings, but the corner was finally reset from the two remaining BTs by observing the directions the scribes faced & by using the recorded distances for the two trees in their respective quadrants. The old blazed section lines also tie in with the restored corner.

Orig. Notes: A basalt stone, now missing 18x10x8" with 4 notches on the south edge & the east edge & from which"

- 16" Fir, bears N.30°E., 7.9 ft. (Yew)
- 8" Cedar, bears S.59°E., 21.1 ft. (now missing)
- 5" Fir, bears S.14°W., 33.0 ft. (Cedar)
- 6" Fir bears N.42°W., 13.9 ft. (now missing)

Restored Corner - 1/2" Brass Rod set from which

- 10" Yew, blown down, but with scribes visible & facing the corner, bears N.77°E., 7.9 ft. (Orig BT.)
- 26" Cedar, scribes visible & facing the corner, bears S.9°W., 33.0 ft. (orig. BT.)
- 58" D.Fir, newly scribed by Shaner, "S 16 BT", bears S.89°E., 58.9 ft.
- 16" D.Fir, newly scribed by Shaner, "T25S, R1W, S8, BT", bears N.36°W., 30.7 ft.

Douglas Co. Surveyors Office - Bruce Rogers, Deputy - W. Stoffel & M. Stone - March 8, 1965 - C.S. file 52/30-16

Found - 26" Cedar, now stump, S.9°W. 33.0 ft. Orig. BT as reported by Shaner, (1960) No trace of scribing nor scar, but stump is only 1.5 ft. tall
58" D.Fir S.89°E. 58.9 ft. scribing visible "S16 BT"
16" D.Fir, blown down, N.36°W. 30.7 ft., scribing visible.

1/2" Brass Rod at Corner. 1960
continued next page

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Cor Secs 8, 9, 16, & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

New BTs- 8" Hemlock S.10°W. 56.0 ft. mkd: S17 CS BT.
12" Hemlock N.85°W. 43.5 ft. mkd: T25S R1W S8 CS BT.
No tree close in NE Quadrant.

BLM resurvey by A. Bert Skeesick & Daniel E. Weller,
Cadastral Surveyor under Group #1888, surveyed Sept.
1998/Sept 1999- (DCSO rec. Vol. 53 Page(s) 20693-4)

The cor. of secs. 8, 9, 16, & 17, perpetuated by Shaner, in
1960, and further perpetuated by Rogers, in 1965, monumented
with a brass rod, ½" dia., firmly set, projecting 6" above
ground, from which the remains of the original bearing trees
A cedar stump, 33" dia., bears S.9°W., 50 lks., no marks
visible. (Record, fir, S.14°W.)
and remains of bearing trees mkd. by Shaner
A fir, 58" dia., bears S.87½°E., 89 lks., with a healed
blaze.
A fir snag, 21" dia., bears N.37¼°W., 46 lks., with trunk
lying alongside, fragmentary scribe marks visible on
partially healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 26" in the
ground directly over the brass rod, with brass cap mkd.

T25S		R1W	
S 8		S 9	
S 17		S 16	
1999			

from which

A fir, 13" dia. bears N.60¾°E. 76 lks. mkd. T25S R1W S9 BT

A fir, 8" dia. bears S.84½°W. 40 lks. mkd. T25S R1W S17 BT

A fir, 9" dia., bears N.53½°W., 32 lks., mkd. X BT.

Deposit a magnet in a white plastic case at the base of the
stainless steel post.