

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 9

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3549)

Set a fir post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., marked ¼ S8 on W & S9 on E faces, from which
A Dogwood, 4" dia., bears S.80°E., 26 lks., mkd ¼ S9 BT.
A Cedar, 5" dia., bears S.76°W., 19 lks., mkd ¼ S8 BT.

Bruce Shaner - For: National Plywood, Inc. - Wit. WM James, & James Griffin - April 21, 1960 - C.S. file 51/92-1

The orig. surveyor misnamed the species of the BTs, read the bearings from the trees to the corner instead of from the corner to the trees, and called one of the distances incorrectly. He also called the streams & ridges on the section line from the south at grossly incorrect distances & fouled up the description of the section corner to the south.
Orig. Notes: A squared Post, from which a:
4" Dogwood bears S.80°E., 17.2 ft.
5" cedar bears S.76°W., 12.5 ft.
Restored: Set a square maple post, from which a:
50" Fir, Orig. ST. with the scribes visible & facing the corner, bears N.80°W., 22.5 ft.
8" Maple, orig. BT with the scribes visible & facing the corner, bears N.76°E., 12.5 ft.
A line bearing due south from the restored corner about ½ chain hits a tree, apparently marked on the original survey as a line tree.

Greg Lang - Crew: Trevor Lang - Aug 2014 - C.S. File 65/86-14

Found - 50" Fir stump with visible scribe bears N.80°W., 22.5 ft. from the corner position. This is an orig. BT according to Bruce Shaner's 1960 retracement.
A clump of maples bears N.76°E., 12.5 ft.
Set - Corner position was determined from the center of a 50" Fir stump with visible scribing using the bearings and distances measured by Shaner in 1960. At the corner position, we set a 5/8"x30" iron rod with plastic cap marked "LANG SURVEYING". The evidence shows this corner has been used for management and harvesting the adjoining lands for many years. Blue flagging and tree blazes were also found along the line which proceeds out of this corner; further verifying its usage.
continued next page

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs- 15" Fir bears S.38 $\frac{1}{4}$ °W., 29.40 ft scribed "¼ S8 BT"
13" Fir bears N.25 $\frac{1}{4}$ °W., 18.00 ft. scribed "¼ S8 BT"
15" Fir bears N.38 $\frac{3}{4}$ °E., 54.30 ft. scribed "¼ S9 BT"
13" Fir bears S.9 $\frac{1}{2}$ °E., 19.20 ft. scribed "¼ S9 BT"

Note - Bearing is to the center of the tree and distance is measured to spike in the side of the tree.
Corner lies in a draw on the south side of accessible ridge.