

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias	Description

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3548)

Set a basalt stone, 16x10x6", 11" in the ground for ¼ sec. cor. mkd. ¼ on N face, from which
 A cedar, 8" dia., bears N.67°E., 15 lks., mkd: ¼ S9 BT.
 A fir, 15" dia., bears S.25°W., 55 lks., mkd: ¼ S16 BT.

V.W. Hosford - For: Evans Products Co. - April 5th thru Nov. 25, 1960 - C.S. File 51/152 & M 20-2

Found - Orig. corner stone in. place.
 The BT for section 16 is dead & down.
 The BT for Section 9 is entirely gone.
New BTs- 10" Hemlock bears N.45°E. 39.8 ft. mkd. ¼ S9 253 BT.
 20" cedar bears S.71°E. 39.0 ft. mkd. ¼ S16 253 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Nov. 18, 1966 - C.S. File 52/30-64

Found - Orig. Stone with partial chisel marks only.
 Orig. 15", now 22" Fir, down & dead, S.25°W. 36.3 ft., scribe visible on opened blaze.
 10", now 14" Hzlock N.45°E. 38.8 ft., shows ¼ S9 253 BT" scribe on unhealed blaze. Alive. 1960
 20", now 24" Cedar S.71½°E. 39.0 ft., shows scribe on unhealed blaze.
Set - Brass Cap at Cor. Mkd: County Surveyors T25S R1W Office, 1966 ¼ S9/S16
 Do not mark new BTs.
Note - This corner lies approx. 32 ft. west of small creek, course South.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 25001006, Surveyed Aug. 2010/April 2011 - (DCSO records Vol. 57 Page(s) 22824)

The ¼ sec. cor. of secs. 9 and 16, perpetuated by Hosford, in 1960, further perpetuated by the Douglas County Surveyor's Office in 1966 from original evidence no longer in existence, monumented with an iron post, 1¼" dia., firmly set, projecting 9" above ground, with a brass cap (properly) mkd. from which the remains of bearing trees mkd. by Hosford
 A roothole bears N.45¾°E., 35.9 ft., downhill of which is a down, decayed hemlock snag, size indeterminate, with scribe marks ¼ S9 253 BT visible on an open blaze.

continued next page

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A cedar snag, 25" dia., bears S.73 $\frac{3}{4}$ °E., 38.5 ft., with scribe marks $\frac{1}{4}$ S9 253 BT visible on a partially healed blaze
and new bearing trees
A cedar, 26" dia., bears N.20°E., 26.1 ft., mkd. $\frac{1}{4}$ S9 BT.
A fir, 15" dia., bears S.54 $\frac{3}{4}$ °E., 17.5 ft., mkd. $\frac{1}{4}$ S16 BT.
Corner is located on a S. slope, 20 ft. W. of a creek, 1 ft. wide, course S.25°W.