

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3536-7)

A fir, 12" dia., for cor. of secs. 9, 10, 15, & 16, I mark T25S S10 on NE, R1W S15 on SE, S16 on SW & S9 on NW sides, with 4 notches on S & 3 notches on E sides, from which
A fir, 12" dia. bears N.50°E., 27 lks mkd: T25S R1W S10 BT
A fir, 14" dia. bears S.61°E., 44 lks mkd: T25S R1W S15 BT
A dogwood, 6" dia., bears S.77°W., 44 lks., mkd: T25S R1W S16 BT.
A cedar, 5" dia. bears N.41°W. 28 lks. mkd: T25S R1W S9 BT

V.W. Hosford - For: Evans Products Co. - April 5th thru Nov. 25, 1960 - C.S. File 51/152 & M 20-2

Found - Badly decayed stump of the orig. corner tree.
6" dogwood BT for sec. 16.
New - Drove a 1 3/4" iron pipe & mkd new BTs.
8" Hemlock bears N.58 1/2°E., 27.3 ft. mkd: S10 253 BT.
32" Fir bears S.86 1/2°E., 12.4 ft. mkd: S15 253 BT.
6" Dogwood bears S.77°W., 29.0 ft. Old BT, scribed in bark.
16" fir bears N.27 1/4°W., 23.8 ft., mkd: S9 253 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Nov. 1966 - C.S. File 52/30-53

Found - 1 1/2" I. Pipe as recorded in 1960
8", now " Hemlock N.58 1/2°E. 28.3 ft. (not 27.3 ft) Alive.
Orig. 12", now 16" Fir, N.50°E. 17.8 ft., now decayed stump, find axe marks only.
Orig. 14", now 16" Fir decayed Stump, S.61°E. 29.0 ft., find "BT" scribe
All other BTs. down or gone.
Do not set Brass Cap.
New BTs- 11" R.Cedar S.74°E. 49.5 ft. Mkd. T25S R1W S15 CS BT
6" Hemlock S.79°W. 7.8 ft. Mkd. S16 CS BT.
Note - No trees available to N.W. - This corner lies on N-S cutting line, cut off to west.

continued next page

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #1347, surveyed Sept 1986/April 1987 - (DCSO records Vol. 49 Page(s) 18417-8)

The cor. of secs. 9, 10, 15, & 16, perpetuated & recorded by Hosford, in 1960, from original evidence no longer in existence, & further perpetuated & recorded by Tracy, in 1966, monumented with an iron pipe, 1½" dia., loosely set, projecting 18" above ground, from which the remains of a bearing tree mkd. by Hosford:

A root hole, bears N.57°E., 43 lks., with a down hemlock alongside, 10" dia., with scribe marks S10 253 BT visible on partially healed blaze.

and the remains of a bearing tree mkd. by Tracy

A cedar snag, 10" dia., bears S.76°E., 75 lks., with scribe marks T25S R1W S15 CS BT.

and bearing trees of which I have no record

A yew, 14" dia., bears N.55°E., 141 lks., with scribe marks S10 BT visible on open blaze.

A sawed fir stump, 35" dia., bears S.69°W., 32 lks., with scribe mks S16 BT visible on open blaze.

A root hole, bears N.78°W., 32 lks., with a down fir alongside, 20" dia., with healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia. 24" in the ground, directly over the iron pipe, with brass cap mkd.

T25S	R1W
<u>S 9</u>	<u>S 10</u>
S 16	S 15
1987	

from which new bearing trees

A fir, 3" dia., bears S.33°E., 31 lks., Mkd. X BT.

A fir, 7" dia. bears S.81°W., 81 lks. mkd. T25S R1W S16 BT

A fir, 4" dia., bears N.20°W., 129 lks., mkd. X BT.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 25001006, Surveyed Aug. 2010/April 2011 - (DCSO records Vol. 57 Page(s) 22823)

The cor. of secs. 9, 10, 15, & 16, monumented with an iron post, 2½" dia., firmly set, projecting 7" above ground, with a brass (properly) mkd.

from which the remains of BTs mkd. by the Douglas County Surveyor's Office in 1966

A decayed cedar snag, 8" dia., bears S.76°E., 49.5 ft., with scribe marks T25S R1W S BT visible on an open blaze.

continued next page

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor Secs 9, 10, 15, & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the remains of bearing trees mkd. by person(s) unknown, reported by Rogers in 1986-87

A yew, 17" dia., bears N.55°E., 93.1 ft., with scribe marks BT and other fragmentary scribe marks visible on a partially healed blaze.

A sawed, decayed fir stump, 35" dia., bears S.69°W., 21.1 ft., with no marks visible.

and bearing trees mkd. by Rogers in 1986-87

A fir, 10" dia., bears S.33°E., 20.5 ft., with a healed double blaze.

A fir, 16" dia., bears S.81°W., 53.5 ft., with a healed blaze.

A fir, 13" dia., bears N.20°W., 85.1 ft., with a healed double blaze.

Corner is located 45 ft. E. of a wide spur, slopes North.