

PRIMARY CORNER DESCRIPTION Cor. Secs 14, 15, 22, & 23

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 8 Page(s) 3523)

Set a cedar poet, 3 ft. long, 4" sq., 24" the ground for cor. of secs. 14, 15, 22, and 23, mkd. T25S S14 on NE, R1W S23 on SE, S22 on SW, & S15 on NW faces with 3 notches on S & 2 notches on E edges, from which

- A Cedar, 15" dia., bears N.87°E., 19 lks., mkd T25S R1W S14 BT.
- A Cedar, 25" dia., bears S.79½°E., 15 lks., mkd T25S R1W S23 BT.
- A Dogwood, 5" dia., bears S.51°W., 17 lks., mkd T25S R1W S22 BT.
- A Hemlock, 8" dia., bears N.69°W., 37 lks., mkd T25S R1W S15 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Clete Putman - Oct. 1962 - C.S. File 52/30-5

Found - Rotten Hemlock Snag N.69°W. 24.4 ft., good scribing visible on old face "R1W S15"
Rotten Cedar Snag N.87°E. 12.5 ft. Fragments of scribing visible on badly rotted face.
Red Cedar Tree, now 38", S.79½°E., 9.9 ft. scar faintly visible. Did not open.
SW BT not found.

Set - Brass Cap at Cor. mkd: County Surveyors Office 1962
T25S R1W S 15 | S 14
 S 22 | S 23

New BTs- 6" Hemlock S.51½°W. 23.8 ft mkd, T25S R1W S22 CS BT
15" R.Cedar N.62°W. 29.0 ft. mkd: T25S R1W S15 CS BT
38" R.Cedar S.79½°E. 9.9 ft. mkd: T25S R1W S23 CS BT
No tree available to NE - Corner lies approx. 200 ft. W of Road.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Nov. 1966 - C.S. File 52/30-38

Found - 1962 C.S. Brass Cap, property mkd.
15" R.Cedar N.62° W. 29.0 ft. Alive, scribe visible on unhealed blaze.
38" R.Cedar S.79½°E., 9.9 ft. Alive, scribe visible upper blaze, lower blaze, burned, rescribe "BT" This tree also orig. BT.
SW renewal BT, down & out of place. Orig. BTs destroyed.

New BTs- 5" Hemlock N.60°E., 85.9 ft. Mkd. "S14 CS BT".
continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 14, 15, 22, & 23

Alias	Description
Alias	Description
Alias	Description
Alias	Description

24" D.Fir Stump S.40°W. 63.4 ft. Mkd. "T25S R1W S22 CS BT"
Note - This corner lies approx. 200 ft. W of road at cutting corner, timber in Section 15 only.

Douglas Co. Surveyors Office - Karen Reed - Pete Earle - July 22, 1979 - C.S. File 60/34-5

Found - A 1962 County brass cap properly marked. 1966
A burnt cedar stump bears N.87°E., 12.2 ft. size indeterminate. Orig.)
A 25" cedar, now 45" rescribed "T25S R1W S23 CS BT" (1962) "BT" rescribed (1966) bears S.79½°E.. 9.9 ft. (orig.)
A 15" R.Cedar, now 20" bears N.62°W., 29.0 ft. scribed "T25S R1W S15 CS" in partially healed blaze. 1962
A 5" Hemlock now 9" bears N.60°E.. 85.9 ft. scribed "S14 CS BT".
A 24" Fir stump, now 30", 6 ft. high bears S.40°W., 63.4 ft. scribe, "T25S R1W S22 CS BT"
A 3" Fir bears N.70°E., 20.2 ft. scribed "X BT". (unrecorded)
A 6" Fir bears S.9°W., 56.3 ft. scribed "T25S R1W S22 BT" (unrec.)
200 ft. west of Rd. 25-1-25.
NO NEW ACCESSORIES SET

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 25001006, Surveyed Aug. 2010/April 2011 - (DCSO records Vol. 57 Page(s) 22816)

The cor. of secs. 14, 15, 22, & 23, perpetuated by Godfrey, in 1962, subsequently perpetuated by the Douglas County Surveyor's Office in 1966 and in 1979, monumented with an iron post, 1¼" dia., firmly set, projecting 11" above ground, with a brass cap (properly) mkd.
from which the remains of the original bearing trees
A burnt, decayed cedar stump, size indeterminate, bears N.87°E., 12.5 ft., with no marks visible.
A cedar, 47" dia., bears S.79½°E., 9.9 ft., with fragmentary scribe marks visible on an open blaze.
and a bearing tree mkd. by Godfrey
A cedar, 32" dia., bears N.64°W., 29.0 ft., with a healed blaze.
and the remains of bearing trees mkd. by the Douglas County Surveyor's Office in 1966
continued next page

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Cor. Secs. 14, 15, 22, & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A hemlock, 20" dia., bears N.58¼°E., 86.4 ft., with no marks visible.
A sawed, decayed fir stump, size indeterminate, bears S.38½°W., 62.3 ft., with a healed blaze.
and bearing trees mkd. by person(s) unknown, reported by the Douglas County Surveyor's Office in 1979
A fir, 12" dia., bears N.69¾°E., 20.3 ft., with a healed double blaze and a metal tag mkd. JEJ 1978.
A fir, 17" dia., bears S.8¼°W., 56.2 ft., with a healed blaze.