

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3525)

Set a fir post, 3 ft. long, 3" sq. 24" in the ground for ¼ sec. cor., marked ¼ S15 on W, S14 on E faces, from which
 A cedar, 12" dia., bears N.46°E., 22 lks., mkd: ¼ S14 BT.
 A hemlock, 5" dia., bears S.63°W., 21 lks., mkd: ¼ S15 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Clete Putnam- June 1962 - C.S. File 52/30-7

Found - Hemlock stump, now 11" dia., S.63°W., 13.9 ft., cut open scar & fd. good scribing "B"
 Red cedar tree, now 20" N.46°E., 14.5 ft., shows good scar. Did not open.
 Corner lies at edge of cut bank about 15 ft. high along edge of road.

Set - Wit. Cor. 10 ft. North of true corner. Iron pipe with brass cap mkd: County Surveyors Office 1962 T25S R1W WC S15|S14 10 ft. S. to ¼ cor.
 Rescribed 20" Cedar East 11.0 ft. (from WC) mkd: "WC ¼ S14 CS BT"

New - 8" Hemlock N.66°W., 16.0 ft. mkd: WC ¼ S15 CS BT.

Fd. Ok DCSO V.R. Tracy - Nov. 1966 C.S. 52/30-54A

BLM Dependent resurvey by James E. Jelley, Cadastral Surveyor under Group #350 & 929 surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16365-6)

The ¼ sec. cor. of sees. 14 & 15, perpetuated & recorded by Godfrey, in 1962, monumented with a mound of stone, 2 ft. base, 1 ft. high, from which the remains of the original BTs:
 A cedar, 24" dia., bears N.46°E., 22 lks. with fragmentary scribe marks visible on decayed blaze & scribe marks WC ¼ S14 CS BT visible on open blaze (Remarked by Godfrey)
 A hemlock stump, 11" dia., bears S.68°W., 21 lks., with scribe marks BT visible on open blaze (Record, S.63°W.)

At the corner point
 Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.
 T25S R1W
 ¼
 S 15|S 14
 1978

from which a new BT
 A pine, 5" dia., bears N.59½°W., 26 lks., mkd. ¼ S15 BT.
 continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From this point, a WC, established by Godfrey in 1962, bears North, 0.17 chs., monumented with an iron post, 1¼" dia., firmly set, projecting 6" above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE T25S R1W WC S15 S14 10 FT S to ¼ COR 1962, from which the remains of a BT mkd. by Godfrey:

A hemlock snag. 9" dia., bears N.66°W., 24 lks., with scribe marks ¼ S15 CS WC BT visible on open blaze.

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #1440, surveyed July/Aug 1988 - (DCSO records Vol. 49 Page(s) 18661-2)

 The ¼ sec. cor. of secs. 14 & 15, monumented with an iron post, 1½" dia., loosely set, projecting 10" above ground, with brass cap mkd. T25S R1W

¼
 S 15|S 14
 1978

from which the remains of the orig. BTs

A cedar, 26" dia., bears N.46°E., 22 lks., with fragmentary scribe marks visible on opened blaze.

A sawed hemlock stump, size indeterminate, bears S.68°W., 21 lks., no marks visible.

and a BT mkd. by Jelley

A pine, 7" dia. bears N.59½°W., 26 lks. with healed blaze. Reset the iron post 24" in the ground.

From this point, the WC established by Godfrey, in 1962, bears North, 0.170 chs., monumented with an iron post, 1¼" dia., firmly set, projecting 6" above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE T25S R1W S15 S14 10 FT S to COR 1962, from which the remains of a BT mkd. by Godfrey:

A hemlock snag, 9" dia., bears N.66°W., 24 lks., with fragmentary scribe marks visible on partially healed double blaze.

The corner is located on the W. edge of road, in cutbank.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 25001006, Surveyed Aug. 2010/April 2011 - (DCSO records Vol. 57 Page(s) 22818)

 The ¼ sec. cor. of secs. 14 & 15, monumented with an iron post, 2½" dia., firmly set, top flush with ground, with a brass cap (properly) mkd.

from which the remains of an original bearing tree

A cedar, 28" dia., bears N.39¼°E., 14.5 ft., with axe marks visible on a partially healed blaze, and an additional healed blaze on W. face. (Record, N.46° E.)

continued next page

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the remains of a bearing tree mkd. by Jelley, reported by Rogers in 1988

A pine snag, 8" dia., bears N.63½°W., 17.2 ft., with a healed blaze. (Record, N.59½°W.)

and a new bearing tree

A cedar, 6" dia., bears N.52¼°W., 13.8 ft., mkd. ¼ S15 BT. From this cor., a point established as WC by Godfrey, in 1962, reported by Rogers in 1988, bears N.4°56'30"W., 11.09 ft., (Record, North, 11.22 ft.), monumented with an iron post, 1¼" dia., firmly set, projecting 12" above ground, with a brass cap mkd. COUNTY SURVEYORS OFFICE T25S R1W W.C. S15 S14 10 FT. S. TO 1/4 COR. 1962, from which the remains of a bearing tree mkd. by Godfrey, reported by Rogers

A decayed hemlock snag, 9" dia., bears N.66°W., 15.8 ft., with fragmentary scribe marks visible on a partially healed double blaze.

From the cor. S.0°57'59"E., at:

30 ft., gravel road, 9 ft. wide, bears N.55°E. and S.55°W. 170 ft., head of a waterfall of a creek, 10 ft. wide, course N.55°E.

Corner is located on the SE. slope of a road cut bank.