

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3526)

Set a yew post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., marked ¼ S11 on N, S14 on S faces, from which
 A hemlock, 4" dia., bears N.45°W., 11 lks., mkd: ¼ S11 BT.
 An alder, 10" dia., bears S.56°E., 5 lks., mkd: ¼ S14 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Nov. 2, 1966 (added 1/19/2021) - C.S. File 52/30-46

Found - Orig. 4" now 5" hemlock N.45°W., 7.3 ft. previously opened & shows "¼ S11" scribe and good BT scar. Also very badly decayed remnants of orig. 10" alder S.56°W., 3.3 ft. no scribe fd.
 Find steel pipe with alum. cap mkd:
 "U.S.P.C. PROPERTY COR T25S R1W 11/14 ¼ RE 4287" and BTs as follows
 26" W.Fir N.32½°W., 30.0 ft scribed "¼ S11 BT"
 24" cedar S.17°E., 43.6 ft. scribed "¼ S14 BT"

Note - New BTs & cap unrecorded.
 This cor. Lies approx 125 ft. west of Canton Creek.

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #1440, surveyed July/Aug 1988 - (DCSO records Vol. 49 Page(s) 18658)

The ¼ sec. cor. of secs. 11 & 14 perpetuated but not recorded by Thomas E. Shrum, Jr., Registered Engineer No. 4287, in 1964, monumented with an iron post, 1" dia., firmly set, projecting 4" above ground, with aluminum cap mkd.

U S P C PROPERTY COR
 T 25 S R 1 W
 11 ¼
 14
 RE 4287

from which the remains of an original BT
 A hemlock snag, 5" dia., bears N.45°W., 11 lks., with scribe marks ¼ S11 visible on open blaze.
 and bearing trees mkd. by Shrum
 A cedar, 25" dia., bears S.17°E., 65 lks. with fragmentary scribe marks visible on partially healed double blaze.
 A fir, 30" dia., bears N.33°W., 45 lks., with fragmentary scribe marks visible on partially healed double blaze.