

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 8 Page(s) 3512)

-----  
A fir, 36" dia., for 1/4 sec. cor., I mark 1/4 S13 on N & S24 on S sides, from which  
    A Fir, 14" dia., bears S.50°W., 67 lks., mkd: 1/4 S24 BT.  
    A Dogwood, 4" dia., bears N.10°E., 35 lks., mkd: 1/4 S13 BT.

G. Robert Lecklider - For: U.S. Plywood Corp - Jan. 1959 - M11-23

-----  
Found - 50" Fir at corner  
          18" Fir, S.50°W., 44.2 ft.  
Set - 48" Fir, S.38 1/2°W., 18.8 ft.  
      50" Fir, N.38 1/2°E., 35.3 ft.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Nov. 1966 - C.S. File 52/30-36

-----  
Found - Orig. Corner Tree, now 50" Fir Stump, shows scar.  
          48" Fir, now stump, S.38 1/2°W. 18.8 ft., shows scribe on unhealed blaze.  
          50" Fir, now stump, N.38 1/2°E. 35.3 ft., shows scribe on unhealed blaze.  
          Orig. BTs gone completely.  
Set - We drive 1/2"x30" I.R. in center of stump & set Brass Cap at base on West side of Corner Stump mkd.  
          County Surveyors 1/4 S 13 T25S R1W  
                                  Office, 1966 S 24  
New BTs- 10" W.Fir N.13°E., 71.6 ft. mkd. 1/4 S13 CS BT.  
          6" I.Cedar N.58°E. 84.9 ft. mkd. 1/4 S13 CS BT.  
No trees available in Sec 24. - Bear. & distances to I. Rod.