

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 700478

PRIMARY CORNER DESCRIPTION C C for Secs. 7 & 18 only, T25-1E

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Resurvey by Joseph A. Ganong and John G. Collins,  
Cadastral Surveyors, Under special instructions dated March  
12, 1921 - (DCSO records Vol. 21 Page(s) 9117)

-----  
Set an Iron post 3 ft. long, 2" dia., 28" in the ground for  
closing cor. of secs. 7 and 18, with brass cap marked

T25S		T25S	
		S 7	
R1W		S 18	CC
S 13		R1E	
		1927	

from which

A Fir 30" dia., bears N.24°E., 137 lks. dist. mkd. T25S  
R1E S7 CC BT.

A Fir 16" dia., bears S.37½°E., 151 lks. dist. mkd. T25S  
R1E S18 CC BT.

Survey by William Ruppert, LS #866 - For: U.S. Forest Service  
- Nov. 1978 - C.S. File 58/176-12D

-----  
Found - 1927 GLO brass cap, properly mkd. on 1½" pipe. Both  
had slid several feet down hill with pile of  
stones.

38" D.Fir N.23°49'E., 90.5 ft., shows good scar.

22" D.Fir S.36°06'E., 97.3 ft., shows good scar.

I RESET orig. pipe with brass cap, S.00°58'E., 1.32 ft. from  
the pipe had previously set for the witness corner to the  
corner of secs. 12 and 13. I constructed a mound of stones  
around it.