

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 30

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Hezikiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3645)

-----  
Set basalt stone 16x10x8", 11" in the ground for ¼ sec. cor. marked ¼ on N face, from which

A cedar, 16" dia., bears N.14°E., 27 lks., mkd: ¼ S19 BT.

A hemlock, 8" dia., bears S.38°W., 25 lks., mkd: ¼ S30 BT.

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #350, surveyed April 1962 -(DCSO records Vol. 32 Page(s) 13238)

-----  
The sec. cor of secs. 19 & 30, monumented with a basalt stone, 16x10x8", loosely set 10" in the ground, marked on the N face, from which the original bearing trees:

A cedar, 27" dia., bears N.14°W., 27 lks., with a healed blaze. (Record bearing, N.14°E.)

A down, hemlock, 16" dia., bears S.38°W., 25 lks., with scribe marks 4 S3 visible on opened blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 12" in the ground to solid rock, and in a mound of stone, 4 ft. base, to top, with brass cap marked

¼  $\frac{S\ 19}{S\ 30}$

T25S R2W

1962

from which a new bearing tree

A cedar, 10" dia., bears S.44½°E., 29 lks. marked ¼ S30 BT

Deposit the original corner stone alongside the iron post.

BLM Dependent resurvey by Richard J. Dieckmann, Cadastral Surveyor, under Group No. 2749 , surveyed Aug. 2014/April 2015 - (DCSO records Vol. 58 Page(s) 23343)

-----  
The ¼ sec. cor. of secs. 19 & 30, monumented with an iron post, 2½" dia., firmly set, projecting 4" above a mound of stone, 3 ft. dia., 18" high, with a brass cap (properly) mkd. from which the remaining original bearing tree

A red cedar, 41" dia., bears N.14°W., 17.8 ft., with a healed blaze.

and the remains of the bearing tree mkd. by Brooks in 1962

A red cedar stump, 17" dia., 5 ft. high, bears S.44½°E., 19.1 ft., with a healed, decayed blaze.

and a new bearing tree

A hemlock, 9" dia., bears S.68¾°E., 8.8 ft., mkd. ¼ S30 BT