

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 200220

PRIMARY CORNER DESCRIPTION S 1/16 S29 & S30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor & Robert Browning, Surveying Technician, under Group #1659, surveyed June/July 1993 - (DCSO recs Vol. 51 Pages 19419)

Point for the S 1/16 sec. cor. of secs. 29 and 30.
Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

S 1/16
S 30 | S 29
1993

from which

A hemlock, 7" dia., bears N.44°E., 33 lks., mkd. X BT.

A fir, 13" dia., bears S.32°E., 115 lks., mkd. S 1/16 S29 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

The corner is located in the edge of timber, with clearcut to the west.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/2/2024 - C.S. File 67/59-8

Found - ¾" BLM brass cap, proj 4" in rough stone mound, cap is oriented South.

Burnt-dead 14" Hemlock N.44°E., 21.7 ft (rec. 33 lks) blaze burned out, add ¾" mag nail right side center.

Burnt-dead 21" Fir S.32°E., 76.1 ft. (rec. 115 lks) fully healed single blaze, add ¾" mag nail right side center.

Galvanized post 1.0 ft. West.

Note - Area burnt 9/2020

Compass decl. 14¼°E.

Mon on relative flat ground. SE quad is burnt old reprod. Rest is clearcut. Line of burnt timber runs North from corner.

Oregon Coordinate Reference System

Cottage Grove - Canyonville Zone

N 192975.182 E 259891.243