

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 200460

PRIMARY CORNER DESCRIPTION N 1/16 Secs 17 & 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Baughman Surveying Service, Glen Baughman - For: Weyerhaeuser Co. - January 1976 - M56-35

Set - 1"x28" iron pipe, set 24" in ground, from which:
A 10" D.Fir bears S.79°E., 14.3', scribed N1/16 S17 BT.
8" D.Fir bears S.39°W., 11.3' scribed N1/16 S18 BT.
20" D.Fir bears S.20½°W., 24.9' w/"W" nail set in base with Weyerhaeuser tag.

Ron Quimby - For: Roseburg Resources - 2/2014 - M167-34B

Found - 1" iron pipe per M56-35
14" Fir, down, bears S.79°E., 14.3 ft., healed scar.
22" Fir stump, bears S.39°W., 11.3 ft., healed scar.
New - 8" Fir bears N.65°E., 3.2 ft. scribed "N1/16 S17 BT"
7" Fir bears S.83°W., 8.6 ft. scribed "N1/16 S18 BT"
Note - Trees were blazed and painted red. BTs scribed per the 2009 Manual of Survey instructions.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 5/23/2023 - C.S. File 67/56-23

Found - 1" iron pipe up 6"
14" Fir S.79°E., 14.3 ft. burned roots.
Burned, dead, 8" fir N.68°E., 3.5 ft. (rec. N.65°E., 3.2 ft.) fully healed double blaze, face burnt, add 3½" mag. nail, right side center.
New - Burned, dead, double trunk 23" cedar S.50°W., 18.0 ft., 3½" mag nail right side center.
Note - Area burnt 9/2020
Compass decl. 14½°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 206349.640 E 259909.029