

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 240240

PRIMARY CORNER DESCRIPTION Center 1/4 Sec 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor & Robert Browning, Surveying Technician, under Group #1659, surveyed June/July 1993 - (DCSO records Vol. 51 Page 19424)

Point for the center ¼ sec. cor. of sec. 29, at intersection with the E and W centerline.

Set a stainless steel post, 28" long, 2½" dia., 28" in the ground, with brass cap mkd. T25S R2W
C¼ S 29
1993

from which

A cedar, 8" dia., bears S.26¾°E., 45 lks., mkd. C¼ S29 BT

A hemlock, 13" dia. bears S.68½°W., 15 lks. mkd. C¼ S29 BT

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 4/2/2024 - C.S. File 67/57-49

Found - BLM brass cap up 2".
Burned dead 12" R.Cedar S.26¾°E., 30.5 ft. (rec. 45 lks 29.7 ft) burned out face, add 3½" mag nail right side center.
Burnt sawn 18"x3' Hemlock stump S.68½°W., 10.6 ft. (rec. 15 lks 9.9 ft) fully healed single blaze add 3½" mag nail top center.

Note - Mon on steep North slope 50' North of skid rd landing.

Area burnt 9/2020

Compass decl. 14½°E.

Burned forest to East, clear cut to west.

Oregon Coordinate Reference System

Cottage Grove - Canyonville Zone

N 194278.884 E 262539.126