

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 347100

PRIMARY CORNER DESCRIPTION No. 1/4 cor. for Sec. 4 only, T26-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 9 Page(s) 3582)

Set Cedar post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. corner mkd. ¼ on N. face, from which
A Cedar 12" dia., bears S.20°W., 30 lks. dist. mkd. ¼ S BT.
A Cedar 6" dia., bears N.30°E., 16 lks. dist. mkd. ¼ S BT

GLO survey by C.M. Collier, Deputy Surveyor, under Instructions dated May/Sept. 1913 - (DCSO records Vol. 10 Page(s) 4271)

I find remains of old post, mkd. and witnessed as described by the Surveyor General. The post almost decayed. I destroy this cor. and re-establish it in the same place, as follows; Set a Cedar post 3 ft. long, 3' sq., 24" in the ground for ¼ sec. cor. of 4 only, mkd. ¼ S4 on S. face, witnessed by the original bearing trees as follows:
A Cedar 10" dia., bears N.30°E., 16 lks. dist. mkd. ¼ S BT.
A Cedar 16" dia., bears S.20°W., 30 lks. dist. mkd. ¼ S BT

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Aug. 1967 - C.S. File 54/40-58

Found - Orig. 10" now 16" Cedar, alive, N.30°E., 10.6 ft., scribe marks visible on unhealed blaze.
Orig. 16" now 32" Cedar, alive, S.20°W., 19.8 ft. shows good scar. Rescribe "¼ S4 CS BT"

Set Brass cap at cor. mkd: County Surveyors Office
T25S R2W ¼ S 4
T26S
1967

New BT - 16" Cedar S.72°E., 19.6 ft. mkd. ¼ S4 CS BT.
Corner lies on bench approx. 400 ft. N. of top of ridge, course NE. and SW.
Excavating to set brass cap, we find remains of old corner post.

Cor. Fd. OK and used in BLM Resurvey by Daniel Berry; Harvey Wofford; G. Steven Popken, Cadastral Surveyors, under Group #'s 786, 848 and 854. And Glenn S. Baughman, L.S. #536, under Contract #52500-CT5-1116, Surveyed July 1972/Oct. 1975 - (DCSO records Vol. 36 Page(s) 15103)

continued next page

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2919, surveyed May 2018/July 2020 - Approved 3/2021 & Added 2/2022 (DCSO records Vol. 59 Page(s) 23912-3)

The ¼ sec. cor. of sec. 4 only, on the N. bdy. of the Tp., monumented with an iron post, 1¼" dia., firmly set, projecting 13" above ground, with a brass cap (properly) mkd. from which the remains of an original bearing tree

A roothole bears S.20°W., 19.8 ft., alongside of which is a down cedar, 26" dia., with a healed blaze. and the remains of a BT mkd. by the Douglas County Surveyors Office in 1967, reported by Berry, Wofford, Popken, and Baughman in 1972-75

A roothole bears S.72°E., 19.8 ft., alongside of which is a down cedar, 18" dia., with a healed blaze. and new bearing trees

A fir, 9" dia., bears S.62½°E., 24.5 ft., mkd. X BT

A fir, 16" dia., bears S.38½°W., 33.7 ft., mkd. ¼ S4 BT. Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center & each monument established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. Angle iron driven alongside each monument.

Ron Quimby - Crew: N. Fromdahl, L. Heddens & J. Ogden - 10/2020 - C.S. File 65/106-58

Found - 1967 BLM brass cap (properly marked)
33" burnt cedar down S.20°W., 19.8 ft.
23" burnt cedar down S.72°E., 19.6 ft.
8" burnt fir S.68°E., 24.5 ft. open scar (no record)
(See above 2/2022)
15" burnt fir S.38°W., 33.7 ft. visible scribe (no record) (See above 2/2022)

New - 5/8"x30" I.Rods with yellow plastic cap stamped "ie ENGINEERING" with post alongside:
N.32°E., 7.8 ft. S.47°E., 9.3 ft.
S.22°W., 10.0 ft. N.67°W., 6.3 ft.

Note - Compass decl. 15½°E.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 3-1/2022 (Filed 4/18/2022) - C.S. File 67/52-25

Found - 2½" DCSO brass cap (properly mkd), projecting 12" in rough mound of stone.
33" burnt cedar down S.20°W., 19.8 ft to roothole
1883 Continued next page

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 347100

PRIMARY CORNER DESCRIPTION No. 1/4 cor. for Sec. 4 only, T26-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

23" burnt cedar down S.72°E. 19.6 ft to roothole 1967
8' burnt Fir S.62°E., 24.7 ft to 3½" PK right side
center (rec. S.68°E., 24.7 ft.) 2020 BLM
15"x7 ft. Fir stump S.38°W., 33.9 ft. to 3½" PK nail
right side center (Rec. 33.7) 2020 BLM
i.e. Engineering 2020:
(N.32°E., 7.8 ft. rec.) N.35°E., 7.8 ft.
(S.22°W., 10.0 ft. rec.) S.16°W., 10.5 ft.
(S.47°E., 9.3 ft. rec.) S.49°E., 9.8 ft.
(N.67°W., 6.3 ft. rec.) N.67°W., 6.1 ft.
Note - Monument is in a burned over area in an E-W cut
line, clear cut to south area. Monument is
approx. 300 ft. west of graveled rd.
Area burnt 9/2020
Compass decl. 14½°E.
Lat: 43°20'37.83" N Long: 122°56'28.87" W