

PRIMARY CORNER DESCRIPTION Cor. Secs 3, 4, 9, & 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3624)

Set a basalt stone 16x10x6", 11" in the ground for cor. for cor. of secs. 3, 4, 9, & 10 marked with 5 notches on S & 3 notches on E edges, from which

- A yew, 8" dia. bears N.30°E., 96 lks., mkd: T25S R2W S3 BT
- A hemlock, 24" dia., bears S.25°E., 30 lks., mkd: T25S R2W S10 BT.
- A yew, 8" dia. bears S.66°W., 104 lks. mkd: T25S R2W S9 BT
- A cedar, 12" dia., bears N.45°W., 24 lks., mkd: T25S R2W S4 BT.

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page(s) 13348)

The cor. of secs, 3, 4, 9, & 10 monumented with a basalt stone, 15x10x8", firmly set, marked with 5 notches on the S. & 3 notches on the E. edges, from which the orig. BTs:

- A yew, 12" dia., bears N.27¼°E., 96 lks. scribe marks T25S R2W S3 BT. visible. (Record bearing, N.30°E.)
 - A hemlock stump, 30" dia., bears S.28½°E., 31 lks., scribe marks 25S 2W BT visible. (Rec. bears S.25°E., 30 lks.)
- The NW and SW bearing trees are both fallen; they can be identified but their original positions cannot.

At the corner point

Set an iron post, 36" long, 2" dia., 28" in the ground, with brass cap mkd.

T25S	R2W
<u>S 4</u>	<u>S 3</u>
S 9	S 10
1951	

from which

- A maple, 8" dia. bears N.10°E. 50 lks. mkd. T25S R2W S3 BT
 - A hemlock, 22" dia., bears S.25½°E., 98 lks. mkd. T25S R2W S10 BT.
 - A hemlock, 8" dia., bears S.33°W., 66 lks., mkd. T25S R2W S9 BT.
 - A yew, 16" dia. bears N.67°W., 89 lks. mkd. T25S R2W S4 BT
- Bury the original corner stone alongside the iron post.

FD. BC & 3 BTs by G. Lang, 2/1992, M114-57

continued next page

PRIMARY CORNER DESCRIPTION Cor Secs 3, 4, 9, & 10

Alias	Description

BLM Dependent resurvey by Richard J. Dieckmann, Cadastral Surveyor, under Group No. 2749 , surveyed Aug. 2014/April 2015 - (DCSO records Vol. 58 Page(s) 23338)

The cor. of secs. 3, 4, 9, and 10, monumented with an iron post, 2" dia., firmly set, projecting 5" above the ground, with a brass cap (properly) mkd.

from which the remains of BTs mkd. by Tallett and White in 1951-63

A decayed hemlock stump, size indeterminate, bears S.33°W., 43.6 ft., with fragmentary scribe marks visible on decayed remains of a blaze.

and new bearing trees

A D.Fir, 28" dia., bears N.65¼°E., 47.7 ft., mkd. T25S R2W S3 BT with Mag-Nail placed on left side center, 5 ft. below the face of the blaze.

A D.Fir, 9" dia., bears S.35½°E., 36.1 ft., mkd. T25S R2W S10 BT.

A D.Fir, 13" dia., bears S.18¾°W., 36.9 ft., mkd. T25S R2W S9 BT.

A D.Fir, 5" dia., bears N.40½°W., 23.8 ft., mkd. T25S R2W S4 BT.

The NW. yew bearing tree mkd. by Tallett and White was recovered downed and out of position with no marks visible.

Ron Quimby - Crew: L. Heddens & J. Ogden - 10/2020 - C.S. File 65/106-47

Found - GLO brass cap (properly mkd)
Burnt 28" D.Fir N.66°E., 47.7 ft. Vis. scribe
Burnt 9" D.Fir S.35°E., 36.1 ft. Vis. scribe
Burnt 13" D.Fir S.19°W., 36.9 ft. Vis. scribe
Burnt 6" D.Fir N.40°W., 23.8 ft. Vis. scribe

New - 5/8"x30" Iron rod with plastic cap marked ie engineering . Post alongside rods.
S.85°E., 7.2 ft.
S.89°W., 5.0 ft.
S.2°W., 5.0 ft.
N.7°W., 4.8 ft.

Note - Area badly burnt 9/2020
Compass decl. 15½°E.