

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezikiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3606)

Set a basalt stone 14x10x6" 10" in the ground for ¼ sec. cor marked ¼ on W face, from which

A yew, 8" dia., bears S.81°E., 32 lks., mkd: ¼ S26 BT.

A yew, 5" dia., bears S.80°W., 34 lks., mkd: ¼ S27 BT.

Fd. rock & 2 BTs by G. McChesney 7/1958, added "W" nails & plates - C.S. File 53/112-42

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #350, surveyed April 1962 -(DCSO records Vol. 32 Page(s) 13221)

The sec. cor. of sees. 26 & 27, monumented with a basalt stone, 14x10x6", firmly set 10" in the ground, marked ¼ on the W face, from which the original bearing trees:

A yew, 11" dia., bears S.81°E., 32 lks., with fragmentary scribe marks visible on partly healed blaze.

A yew, 9" dia., bears S.85°W., 34 lks., with no marks remaining on rotted blaze. (Record bearing, S.80°W.)

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

¼
S 27 S 26
T25S R2W
1962

from which a new BT

A fir, 42" dia., bears S.19½°W., 41 lks., mkd: ¼ S27 BT.

Deposit the orig. corner stone alongside the iron post.

BLM dependent resurvey by Daniel Berry, Harvey Wofford, & G. Steven Popken Cadastral Surveyors & Glenn Baughman, LS, under contract #52500-CT5-1116 & Group E 786, 848, & 854, surveyed July 1972/Oct. 1975 - (DCSO records Vol. 36 Page 15118)

The ¼ sec. cor. of secs. 26 & 27, remonumented by Brooks, in 1962, with an iron post, 2½" dia., firmly set, protruding 4" above ground, with brass cap (properly) mkd.

from which the original bearing trees

A yew, 13" dia., bears S.81°E., 32 lks. with healed blaze.

A yew, 10" dia., bears S.85°W., 38 lks. with healed blaze.

and a bearing tree mkd. by Brooks.

A fir, 43" dia. bears S.19½°W., 41 lks. with healed blaze.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor Under Group No. 2317, Surveyed June 2010/June 2011 - DCSO records Vol. 57 Page(s) 22804

The ¼ sec. cor. of secs. 26 & 27, monumented with an iron post, 2½" dia., firmly set, flush with the ground, (alongside of which is a basalt stone 14x10", with no marks visible), with brass cap (properly) mkd.
from which the remains of the original bearing trees
 A yew, 12" dia., bears S.81°E., 21.1 ft., with no marks visible on a decayed blaze.
 A sawed yew stump, 10" dia., bears S.80½°W., 25.1 ft., with no marks visible. (Record, S.85°W.)
and the remains of a bearing tree mkd. by Brooks
 A sawed fir stump, 37" dia., bears S.19½°W., 27.1 ft., with a healed blaze.
and a new bearing tree
 A hemlock, 12" dia., bears S.58¾°W., 21.4 ft mkd. ¼ S27 BT

BLM Dependent resurvey by Richard J. Dieckmann, Cadastral Surveyor, under Group No. 2749 , surveyed Aug. 2014/April 2015 - (DCSO records Vol. 58 Page(s) 23333-4)

The ¼ sec. cor. of secs. 26 & 27, monumented with an iron post, 2½" dia., firmly set, flush with the ground, with a brass cap (properly) mkd.
from which the remaining original bearing tree
 A yew, 12" dia., bears S.81°E., 21.1 ft., with no marks visible on a partially healed blaze.
and the remains of the bearing tree mkd. by Brooks in 1962
 A D.Fir stump, 37" dia., bears S.19½°W., 27.1 ft., with a healed blaze and tin cap.
and the bearing tree mkd. by Skeesick in 2010-11
 A hemlock, 13" dia., bears S.58¾°W., 21.4 ft., with scribe marks ¼ S27 BT visible on a partially healed blaze.
The original SW BT was recovered downed and out of position.

The geographic position in NAD 1983 (2011)
Latitude: 43°21'57.17"N. Longitude: 122°54'51.01"W.