

PRIMARY CORNER DESCRIPTION WC 1/4 Cor. Secs. 23 & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezikiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3607)

Set a basalt stone 16x10x6", 11" in the ground for ¼ sec. cor. marked ¼ on N face, from which

A hemlock, 12" dia., bears N.53°E., 53 lks. mkd: ¼ S23 BT.

A hemlock, 9" dia., bears S.25°E., 31 lks., mkd: ¼ S26 BT.

Fd. OK by G. McChesney, 8/11/1958, C.S. 53/112-40 added "W" nail & plate

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #350, surveyed April 1962 - (DCSO records Vol. 32 Page(s) 13221-2)

The ¼ sec. cor. of secs. 23 & 26, monumented with a basalt stone, 16x10x6", firmly set 11" in the ground, marked ¼ on the N face, from which the orig. with:

A hemlock, 26" dia., bears N.56½°E., 56 lks. with a healed blaze. (Rec. bearing & dist. N.53°E., 53 lks.)

A hemlock, 14" dia., bears S.25°E., 31 lks., with scribe mark 4 visible on partly opened blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 25" in the ground, with brass cap marked:

¼ $\frac{S\ 23}{S\ 26}$

T25S R2W

1962

from which a new BT

A hemlock, 26" dia., bears S.3°E., 70 lks., mkd: ¼ S26 BT.

Deposit the orig. corner stone alongside the iron post.

BLM dependent resurvey by Daniel L. Berry, Harvey E. Wofford, & G. Steven Popken Cadastral Surveyors & Glenn S. Baughman, LS, under contract #52500-CT5-1116 & Group E 786, 848, & 854, surveyed July 1972/Oct. 1975 - (DCSO recs Vol. 36 Page 15120)

The ¼ sec. cor. of secs. 23 & 26, remonumented by Brooks in 1962, w/an iron post, 2½" dia., firmly set, protruding 4" above ground, w/brass cap mkd., from which the orig. BTs

A hemlock, 27" dia. bears N.56½°E., 56 lks. w/healed blaze

A hemlock, 15" dia., bears S.25°E., 31 lks., with scribe mark 4 visible on opened blaze.

and a BT mkd. by Brooks

A hemlock, 28" dia., bears S.3°E., 70 lks. with scribe marks ¼ SD26 B visible on open blaze.

continued next page

PRIMARY CORNER DESCRIPTION WC 1/4 Cor. Secs. 23 & 26

Alias	Description

Douglas Co. Surveyors Office - Stephen J. Flause - Colleen O'Toole - Jan. 27, 1981 - C.S. File 61/19-1

Because of logging, road work and stream in area, the 1962 BLM remonumentation by Brooks is destroyed and after a thorough search of the locale, no evidence of the brass cap & I.P., or the orig. monument stone is fd.

Found - An orig. 12" Hemlock, now a 30" Hemlock stump, uprooted & loose from ground, lies close to record bearing and distance from orig. monument location (as determined from the other orig. BT). This stump has good evidence of a blaze.

An orig. 9" Hemlock now a 13" DBH 6 ft. tall Hemlock snag, bears S.25°E., 20.5 ft. Tree has partially opened double blaze. We open further to find good "1/4" scribing marks.

From 1962 remonumentation, a 26" Hemlock now a 26" DBH 4 ft. tall Hemlock snag bears S.03°E., 46.1 ft. (slope distance) (Rec. S.03°E., 46.2 ft.) Tree has opened single blaze with scribing ¼ S26 BT visible.

Because bearing & distances to evidence or orig. trees agree & the bearing to the remonumentation tree agrees, accept a monument location as determined by this evidence & disregard the slope dist. discrepancy by assuming the dist. to the 1962 BT was measured on the slope. HOWEVER, this orig. position is now virtually in a creek because of nearby road work

Set - A witness corner is placed 10.0 ft. due East of orig. monument location. This witness corner is monumented with a DCSO 2½" brass cap on a 1½" I.P. 30" long., set firmly and protrudes 2" from soil. Cap mkd. "Douglas County Surveyor" T2SS WC S23 S26 ¼ R2W 1981.

New BTs- The orig. SE BT now a 13" DBH Hemlock snag as previously described bears S.04°W., 18.3 ft.

The 1962, 26" Hemlock as prev. described bears S.10°W., 46.8 ft.

A boat spike in a 47" Fir stump bears N.19°E., 6.38 ft. & is stamped "WC BO 1"

A boat spike in a 49" Fir stump bears S.82½°E., 35.87 ft. & is stamped "WC BO 2".

All four bearing objects are tagged with new DCSO BT tags.

continued next page

PRIMARY CORNER DESCRIPTION WC 1/4 Cor. Secs. 23 & 26

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1979, surveyed May 2001/June 2002- (DCSO rec. Vol. 54 Page(s) 20919-20)

The 1/4 sec. cor. of secs. 23 & 26, determined at record bearing & dist. from the remains of an original BT
A sawed hemlock stump, 14" dia., bears S.25°E., 20.5 ft., with fragmentary scribe marks visible on partially healed blaze.
and remains of a BT mkd. by Brooks
A sawed hemlock stump, 26" dia., bears S.3°E., 46.2 ft., with healed blaze.
The corner point is located in creek. Not monumented.
From this point, the WC for the 1/4 sec. cor. of secs. 23 and 26, established by Flause, in 1981, bears East, 10.00 ft., monumented with an iron post, 1 1/2" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd. from which bearing objects mkd. by Flause
A bridge spike driven into top of a fir stump, 48" dia., bears N.19°E., 6.4 ft., mkd. WC B01.
A bridge spike driven into top of a fir stump, 48" dia., bears S.82 1/2°E., 35.9 ft., mkd. WC B02.
and new bearing trees
A fir, 7" dia., bears N.28°E., 25.9 ft., mkd. X BT.
A cedar, 13" dia. bears S.30°W., 13.2 ft. mkd. WC 1/4 S26 BT
A fir, 9" dia., bears N.39 1/4°W., 27.4 ft., mkd. WC 1/4 S23 BT

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor Under Group No. 2317, Surveyed June 2010/June 2011 - DCSO records Vol. 57 Page(s) 22802

The true point for the 1/4 sec. cor. of secs. 23 and 26, determined at record bearing and from the remains of an original bearing tree
A sawed hemlock stump, 14" dia., bears S.25°E., 20.5 ft., with scribe marks /4 visible on a partially healed blaze.
and the remains of a BT mkd. by Brooks, reported by Skeesick
A sawed hemlock stump, 26" dia., bears S.3°E., 46.2 ft., with no marks visible.
The cor. point is located in a creek, 1 ft. wide, course N.75°W., not monumented.
From this cor., a point established by the Douglas County Surveyors Office in 1981 as witness cor. for the 1/4 sec. cor. of secs. 23 and 26, bears East, 10.00 ft., monumented with an iron post, 1 1/2" dia., firmly set, projecting 4" above the ground, with brass cap mkd. DOUGLAS COUNTY SURVEYOR T25S WC 1/4 S23 S26 R2W 1981 and an arrow pointing to the cor., **cont.**

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 541300

PRIMARY CORNER DESCRIPTION WC 1/4 Cor. Secs. 23 & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of bearing trees mkd. by the Douglas County Surveyor's Office, reported by Skeesick

A bridge spike driven into top of a fir stump, 48" dia., bears N.19°E., 6.4 ft. mkd. WC B01.

A bridge spike driven into top of fir stump, 48" dia., bears S.82½°E., 35.9 ft., mkd. WC B02.

and bearing trees mkd. by Skeesick

A fir, 9" dia., bears N.28°E., 25.9 ft., with a healed double blaze.

A cedar, 16" dia., bears S.30°W., 13.2 ft., with scribe marks WC ¼ S26 BT visible on a partially healed blaze.

A fir, 14" dia., bears N.39¼°W., 27.4 ft., with a healed double blaze.