

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3597)

Set a basalt stone 14x9x9", 10" in the ground for sec. cor. marked on W. face, from which,
 A fir, 65" dia., bears N.69°E., 14 lks., marked ¼ S24 BT.
 A fir, 30" dia., bears N.32°W., 24 lks. marked ¼ S23 BT.

V.W. Hosford - Sept. 1957 - C.S. File 42/308-8

Before logging I fd the marked stone corner & the BT for section 24 in good condition. The BT for section 23 was a dead snag with scribing visible. After logging in the S E ¼ of sec 23 & the NW ¼ of section 24, the BT for section 23 has been destroyed. I drove a 1½" iron pipe 36" long 16" in the ground at the West edge of the corner stone, from which:
 A Hemlock 7" dia. bears N.78°W. 66.0 ft. marked S23 253 BT

Glen McChesney, Weyerhaeuser Co. - 5/20/1958 - C.S. File 53/112-39

Found - Iron pipe beside orig. stone.
 72" Fir N.68°E., 9.2 ft. (GLO)
 16" (Fir) stump shell N.32°W., 16 ft. (GLO)
 Hemlock N.78°W., 66 ft. (Hosford)
New - (Orig) 72" Fir N.61°E. 9.3 ft. with "W" nail & plate
 50" Fir S.40°W., 31.0 ft. with "W" nail & plate.

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #350, surveyed April 1962 - (DCSO records Vol. 32 Page(s) 13217)

The sec. cor. of secs. 23 & 24, monumented with a basalt stone, 14x9x9", firmly set 10", in the ground, marked ¼ on the W face, & perpetuated & recorded by Hosford in 1957, by driving an iron pipe, 36", long, 1½" dia., 12" in the ground, alongside the original corner stone from which the orig. BTs:
 A fir, 66" dia., bears N.69°E., 18 lks. with a healed blaze. (Record distance, 14 lks.)
 A rotted fir stump, 30" dia., bears N.37°W., 26 lks., with scribe marks ¼ S23 visible on opened blaze. (Record bearing and distance, N.32°W., 24 lks.)
and a tree marked by Hosford
 A broken hemlock, 8" dia., bears N.80°W., 100 lks., with scribe marks S23 253 BT visible on unhealed blaze on down trunk.
At the corner point
continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs 23 & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1979, surveyed 2001/2002- (DCSO rec. Vol. 54 Page(s) 20909-10)

The 1/4 sec. cor. of secs 23 & 24, perpetuated by Tracy, in 1966. The uprooted monument set by Brooks in 1962 was recovered & reset by Monrean, in 1976, monumented with an iron post, 2 1/2" dia., firmly set, projecting 3" above ground, with brass cap mkd. 1/4

S 23 | S 24
T25S R2W
RESET 1976
1962

from which the remains of a bearing tree mkd. by Tracy
A hemlock stump, 14" dia., bears S.44 3/4°E., 25.1 ft., with healed blaze.

and accessories mkd. by Monrean

A bridge spike driven into top of a fir stump, 61" dia., bears S.18 1/2°E., 16.6 ft., mkd. B02

A bridge spike driven into top of a fir stump, 61" dia., bears S.41 1/4°W., 32.6 ft., mkd. B01

and new bearing trees

A fir, 11" dia., bears S.57 1/4°E., 18.1 ft., mkd. 1/4 S24 BT.

A fir, 13" dia., bears S.29 1/2°W., 24.6 ft., mkd. 1/4 S23 BT.

Each new bearing tree has a 2 1/2"x 1/4" magnetic nail (Mag Nail) driven at the base right side-center.

Fd. 2 BTs w/healed blazes and a 6' steel post set 2' S.87°E.
By D. Edwards 3/2020 - M176-59

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 6/19/2024 - C.S. File 67/58-11

Found - 3 1/4" brass cap (properly mkd), BLM, up 3"
Very rotted-burnt 40"x3 ft. fir stump S.20°E., 18.0 ft. center root crown (rec S.18 1/2°E., 16.6 ft) spike gone.

Very rotted-burnt 48"x4 ft. fir stump S.41 1/4°W., 33.1 ft. (rec. 32.6 ft.) bridge spike in top.

24"x1 ft. D.Fir stump S.57 1/4°E., 17.5 ft. (rec. 18.1 ft) blaze inside, add 3 1/2" mag nail top center.

Burned broken off 20"x25 ft. D.Fir S.29 1/2°W., 24.8 (rec. 24.6) add 3 1/2" mag nail right side center.

Galvanized steel post.

Note - Mon on moderate westerly slope ≈ 35 ft. west of abandoned dirt logging road.

Clear cut to east old reprod to west.

Area burnt 9/2020

Continued next page

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Compass decl. 14¼°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 199769.293 E 280892.006