

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Cor. Secs 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3599)

Set a basalt stone 16x10x6", 11" in the ground for cor. for cor. of secs. 11, 12, 13, & 14 marked with 4 notches on S & 1 notch on E edges, from which
A fir, 38" dia. bears N.25°E. 41 lks. mkd: T25S R2W S12 BT
A fir, 44" dia. bears S.23°E. 15 lks. mkd: T25S R2W S13 BT
A fir, 14" dia. bears S.55°W. 31 lks. mkd: T25S R2W S14 BT
A hemlock, 14" dia. bears N.76°W., 26 lks. mkd: T25S R2W S11 BT.

Glen McChesney, Weyerhaeuser Co. - 1/30/1958 - C.S. 53/112-21

Fd. stone & BTs added "W" nails & plates.

L. Wilson, reported by Glen McChesney, Weyerhaeuser Co. - 10/12/1970 - C.S. File 53/112-22

Found - 1962 BLM BC & stone.
38" Fir stump, N.21°E., 27.1', plate & "W" nail
50" Fir, face overgrown, S.24°E., 9.9', plate & "W" nail
Fir, S.55°W., 20.5', down
18" Hemlock, scribing visible, N.73°W., 17.4'
38" cedar S.76°W., 22.0' - windthrown, plate & "W" nail
44" Fir stump, N.33°W., 18.0 ft., in place, plate & "W" nail
New - Drove 1"x48" monel pipe along north side of stone.
Added 1 new reference with plate & "W" nail on:
8" Hemlock, S.88½°W., 38.7'

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #350, surveyed April 1962 - (DCSO records Vol. 32 Page(s) 13219-20)

The cor. of secs. 11, 12, 13, & 14, monumented with a basalt stone 16x10x6", firmly set 11" in the ground, marked with 4 notches on the S, & 1 notch on the E. edge, from which the orig. BTs:
A fir, 46" dia., bears N.18°E., 43 lks., with healed blaze. (Record bearing & distance, N.25°E., 41 lks.)
A fir, 58" dia., bears S.30°E., 18 lks., with healed blaze. (Record bearing and distance, S.23°E., 15 lks.)
continued next page

PRIMARY CORNER DESCRIPTION Cor Secs 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir snag, 15" dia., bears S.57°W., 31 lks., with scribe marks 25 S R2W S14 visible on unhealed blaze. (Record bearing, S.55°W.)
 A hemlock, 20" dia., bears N.72°W., 26 lks., with scribe marks T25S R2W S11 visible on opened blaze. (Record bearing, N.76°W.)
 At the corner point
 Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T25S R2W	
S 11	S 12
S 14	S 13

 1962 from which a new BT
 A hemlock, 9" dia., bears S.6°W., 72 lks., mkd: T25S R2W S14 BT.
 Deposit the orig. Corner stone alongside the iron post.

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor Group #1979, surveyed 2001/2002- (DCS0 rec. Vol. 54 Pages 20916-7)

 The cor. of secs. 11, 12, 13, & 14, monumented with an iron post, 2½" dia., firmly set, projecting 2 ins. above ground, with brass cap mkd.

T25S R2W	
S11	S 12
S14	S 13

 1962
 from which the remains of the original bearing trees
 A sawed fir stump, 43" dia, bears N.16¾°E., 27.3 ft., with healed blaze. (Record, N.18½°E., 28.4 ft.)
 A roothole bears S.30°E., 11.9 ft., with fallen fir trunk, 60" dia, lying alongside, with healed blaze.
 A decayed fir stump, size indeterminate, bears S.53¾°W., 25.7 ft., with no marks visible. (Rec S.57°W. 20.5 ft)
 A decayed hemlock stump, size indeterminate, bears N.75¾°W., 17.2 ft., with fallen trunk, 22" dia, lying alongside, with healed blaze. (Record, N.72°W.)
 and bearing tree mkd. by Brooks
 A hemlock, 24" dia, bears S.60¼°W., 47.5 ft., with healed blaze. (Record, S.6°W.)
 and new bearing trees
 A fir, 6" dia. bears N.22°E. 11.5 ft. mkd. T25S R2W S12 BT
 A hemlock, 10" dia, bears S.21½°E., 32.1 ft., mkd. T25S R2W S13 BT.
 A hemlock, 10" dia, bears N.48¾°W., 11.8 ft., mkd. T25S R2W S11 BT.
 Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

continued next page

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Cor. Secs. 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 5/4/2023 - C.S. File 67/56-13

Found - BLM brass cap (properly mkd) up 10", rough stone mound around base.

Burned-rotted 38"x3 ft fir stump, S.65¼°E., 24.8 ft.
18"x5 ft. burned cedar stump S.71½°W., 81.6 ft.
(rec. 81.0 ft.)

Burned, dead 16" D.Fir S.7½°W., 25.2 ft. (rec. 25.0 ft) fully healed double blaze, add 3½" mag nail right side center.

Burned-dead, 23" D.Fir N.66½°W., 38.1 ft., fully healed double blaze, add 3½" mag nail right side center.

Steel post 1 ft. east of BC

New - Burned-dead, 16" R.Cedar S.40°W., 24.3 ft., not blazed or scribed, add 3½" mag nail right side center.

8 ft x 30 ft basalt wall NNE 10± ft.

Note - Monument is 470± east of gravel road.

Area burnt 9/2020

Compass decl. 14½°E.

Small stream flows southerly is west 20 ft monument just above bottom of draw.

Oregon Coordinate Reference System

Cottage Grove - Canyonville Zone

N 210270.846

E 280650.476