

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezikiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3603)

Set a basalt stone 15x10x5", 10" in the ground for sec. cor. marked ¼ on W face, from which

A fir, 24" dia., bears S.72°W., 20 lks., mkd: ¼ S2 BT

A fir, 9" dia., bears N.37°E., 37 lks., mkd ¼ S1 BT.

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page(s) 13343)

The Sec. cor. of secs. 1 & 2, monumented with a basalt stone, 12x10x6", firmly set, marked on W. face, from which the original bearing trees.

A fir, 16" dia., bears N.30°E., 37 lks., blaze healed. (Record bearing, N.37°E.)

A fir, 30" dia., bears S.74°W., 22 lks., blaze healed. (Record: bears S.72°W., 20 lks.)

At the corner point

Set an iron post, 36" long, 1" dia., 28" in the ground, with brass cap mkd.

¼
S 2 | S 1
1951

No new accessories established.

Bury the original corner stone alongside the iron post.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2348, Surveyed Aug. 2011 - (DCSO records BLM Plat T25-2W 2012-1 & Vol. 58 Pages 22940-1)

The ¼ sec. cor. of secs. 1 & 2, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

A fir, 26" dia., bears N.30°E., 24.4 ft., with a healed blaze.

A fir snag, 53" dia., bears N.74°W., 4.5 ft., with a healed blaze.

and a new bearing tree

A cedar, 7" dia., bears N.81¼°W., 38.2 ft., mkd. ¼ S2 BT.