

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 640440

PRIMARY CORNER DESCRIPTION Center 1/4 Cor Sec 13

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1979, surveyed 2001/2002- (DCSO rec. Vol. 54 Page(s) 20941)

Point for the center ¼ sec. cor. of sec. 13, at the intersection with the E. and W. centerline.
Set a stainless steel post, 28" long, 2½" dia., 22" in the ground, with brass cap mkd.

T25S R2W
C ¼
S 13
2002

from which

A fir, 16" dia., bears S.35½°E., 18.3 ft., mkd. C ¼ S13 BT

A fir, 19" dia., bears N.75½°W., 42.3 ft., mkd. C ¼ S13 BT

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 7/15/2024 - C.S. File 67/58-25

Found - 3¼" BLM brass cap (properly mkd) on 2" I.D.I.P. up 6" Burned, broken off 18"x7½ ft. Fir stump S.37½°E., 18.8 ft. (rec. S.35½°E., 18.3 ft) partly healed single blaze face burned away, 2½" mag nail fd right side center.

Burned, broken off 22"x6½ ft. fir stump N.75½°W., 42.3 ft., partly healed single blaze, face burned away, fd 2½" mag nail right side center.

New - 5/8"x30" iron rod with DCSO plastic cap, proj 22" from 38"x2 ft. cedar stump N.65½°W., 11.0 ft.

5/8"x30" iron rod with DCSO plastic cap, up 6" S.13°E., 7.5 ft.

Note - Mon in burned reprod on small bench at base of steep north slope.

Mon is ≈ 200 ft south of gravel road.

Area burnt 9/2020

Compass decl. 14¼°E.

Oregon Coordinate Reference System

Cottage Grove - Canyonville Zone

N 205154.581 E 283373.551