

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 640500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 12 & 13

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3600)  
-----  
Set a chinquapin post, 3" dia., 3 ft. long, 24" in the ground for ¼. sec. cor. marked ¼ S12 on N face & S13 on S faces; from which  
    A fir, 15" dia., bears N.34°E., 19 lks., mkd: ¼ S12 BT.  
    A fir, 26" dia., bears S.54°W., 17 lks., mkd: ¼ S13 BT.

A.R. Evans - B.B. Irving & M.E. Godfrey witnesses - Sept. 1949 - C.S. File 43/158  
-----  
Found - 0BTs  
        15" fir (now 20") N.34°E., 19 lks.  
        26" fir (now 30") S.54°W., 17 lks.  
Set - ¾"x30" iron rod for corner at intersection of distances.

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #350, surveyed April 1962 - (DCSO records Vol. 32 Page(s) 13220)  
-----  
The ¼ sec. cor. of secs. 12 & 13, determined at record bearing & distance, from the faces of the original BTs:  
    A fir, 19" dia., bears N.34°E., 20 lks., with healed blaze. (Record distance, 19 lks.)  
    A sawed fir stump, 39" dia., bears S.54°W., 19 lks., with healed blaze. (Record distance, 17 lks.)  
At the corner point  
Set an iron post, 28", long, 2½" dia., 25" in the ground with brass cap mkd:  
                                ¼  $\frac{S\ 12}{S\ 13}$   
  T25S R2W  
  1962  
from which a new bearing tree  
    A hemlock 13" dia., bears South, 43 lks., mkd: ¼ S13 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West- March 1967- C.S. File 54/27-118  
-----  
Found - 1962 Cadastral Brass Cap on 2½" I.P, push out of position & buried 6" below surface of ground.  
Reset - Brass Cap in proper position from BTs  
        1962-13" now 14" Hemlock South 28.4 ft. Alive, badly injured & filled to 3" of top of unhealed scribed blaze.  
  
continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 12 & 13

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Orig. Fir BT, now only shattered remains of sawed stump, S.54°W. 12.5 ft. no scribe found.  
No trace NE BT.  
New BTs- 8" hemlock N.19°E., 141.6 ft. mkd. ¼ S12 CS BT.  
24" Cedar, S.57°W. 51.0 ft. mkd. ¼ S13 CS BT.  
Set - 6' Red steel fence Post alongside Brass Cap. This corner recent logged off unit approx. 200 ft. N of East fork Rock Creek Road.

Howard Johnstone - Feb. 5, 1982 - C.S. File 58/188-6  
-----  
Found - 1962 Cadastral BC. under 10" of dirt and rock with steel fence post alongside.  
39" fir stump bears S.54°W., 12.5 ft.  
16" hemlock bears South, 28.4 ft. (broken off at stump).  
New BTs- 5" D.Fir bears N.89°W., 24.6 ft. (scribed)  
5" D.Fir bears S.20°E., 39.0 ft. (scribed).  
\*Note: brass disc on each face with "RLS 495"  
Note - Corner sets alongside a small dry stream bed - entire area is covered with 1 - 4 feet of dirt & rock that has washed in from up above.

Fd. Ok by S. Ness 10/1995 - M123-3A&B

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor Group #1979, surveyed 2001/2002- (DCS0 rec. Vol. 54 Page 20917)  
-----  
The ¼ sec. cor. of secs. 12 & 13, monumented with an iron post, 2½" dia., firmly set, buried 8" below ground, with brass cap (properly) mkd.  
from which the remains of an original bearing tree  
A decayed fir stump, size indeterminate, bears S.50¾°W., 12.5 ft., with no marks visible. (Record, S.54°W.)  
and remains of a bearing tree mkd. by Brooks  
A decayed hemlock stump, size indeterminate, bears S.3°W., 28.4 ft., with no marks visible. (Record, South)  
and a bearing tree mkd. by Tracy, in 1967  
A cedar, 32" dia., bears S.57¼°W., 50.8 ft., with healed blaze.  
and bearing trees mkd. by Johnstone, in 1982  
A fir, 12" dia. bears S.19°E., 38.5 ft., with healed blaze  
A fir, 12" dia., bears N.88½°W., 24.9 ft., with healed blaze.  
Cor. sits on edge of dry streambed, 5 ft. wide, with steel fence post driven alongside.

continued next page

2

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 640500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 12 & 13

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 5/9/2023 - C.S. File 67/56-15

-----  
Found - 3¼" BLM brass cap (properly mkd), buried 8"  
Burned-hollow, 30"x6 ft. cedar stump S.57¼°W., 50.8  
ft., add 3½" mag nail right side center.  
Burned-rotted 11"x6½ ft. D.Fir stump S.19°E., 38.5  
ft., blaze gone.  
Steel post north 0.3 ft.  
Galv. steel post N.65°E., 2.0 ft.  
New - 5/8"x30" iron rod with DCS0 plastic cap N.75°E.,  
10.8 ft. up 6".  
5/8"x30" iron rod with DCS0 plastic cap N.7°W., 9.2  
ft. up 3".  
Note - Mon. is S.45°E., 30± ft from south edge of small log  
landing.  
Area burnt 9/2020  
Compass decl. 14½°E.  
Lat: 43°24'06.95" N Long: 122°53'04.80" W