TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 700513

PRIMARY CORNER DESCRIPTION N 1/16 S18 only West line, T25-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 929 - Surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16335)

Point for the N 1/16 sec. cor. of sec. 18 only, T25S R1W
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

N 1/16
S 18
1978

from which
A cedar, 5" dia., bears N.78½°E. 53½ lks. mkd N1/16 S18 BT
A cedar, 8" dia., bears S.28¾°E. 103 lks. mkd N1/16 S18 BT

BLM resurvey by A. Bert Skeesick & Daniel E. Weller, Cadastral Surveyors under Group #1888, surveyed Sept. 1998/Sept. 1999 - (DCSO rec. Vol. 53 Page(s) 20705)

The N 1/16 sec. cor. of sec. 18 only, monumented with an iron post, 2½ ins. diam., firmly set, projecting 1 in. above ground, with brass cap (properly) mkd.
from which bearing trees mkd. by Jelley
A cedar, 9" dia., bears N.78½°E., 53½ lks., with a healed blaze.
A cedar, 12" dia., bears S.28¾°E., 108 lks., with a healed blaze. (Record, 103 lks.)

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 5/30/2024 - C.S. File 67/58-8

Found - 3¼" BLM brass cap, proj. 1" (properly mkd)
Burned-dead 17" I.Cedar N.78½°E., 35.3 ft. fully healed single blaze, add 3½" mag nail right side center.
Burned-dead 18" I.Cedar S.28¼°E., 71.3 (rec. dist. not checked due to blow down) fully healed single blaze.
Metal fence post south 0.5 ft.
New - Burned-dead 13" D.Fir S.27°w., 12.8 ft. 3½" mag nail right side center.
Note - Area burnt 9/2020
Compass decl. 14½°E.
Mon on steep West slope 250'± east of N-S. Draw bottom in burnt reprod.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 208489.513 E 286124.411