

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3719)

Set Cedar post, 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 17, 16, 19 and 20, mkd. T25S S17 on NE., R3W S20 on SE., S10 on SW., and S18 on NW. faces, with 3 notches on S. and 5 notches on E. edges, from which
A Fir 30" dia., bears N.10°E., 22 lks dist., mkd.
T25S R3W S17 BT.
A Fir 6" dia., bears S.70°E., 59 lks. dist., mkd.
T25S R3W S20 BT.
A Fir 12" dia., bears S.33°W., 22 lks. dist., mkd.
T25S R3W S19 BT.
A Fir 15" dia., bears N.40°W., 32 lks. dist., mkd.
T25S R3W S18 BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11595)

Proportional measurement. Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor. of secs. 17, 18, 19, and 20, with brass cap mkd.

T25S R3W	
S18 S17	

S19 S20	
1944	from which

A Fir 12" dia., bears N.16½°E., 95 lks. dist., mkd.
T25S R3W S17 BT.
A Fir 12" dia., bears S.64½°E., 48 lks. dist., mkd.
T25S R3W S20 BT.
A Red Cedar 20" dia., bears S.43°W., 13 lks. dist., mkd. T25S R3W S19 BT.
A Fir 42" dia., bears N.49°W., 67 lks. dist., mkd.
T25S R3W S18 BT.

Milo E. Godfrey and Crew - Nov. 7, 1962, C.S. File 49/102-9

Found - GL0 pipe and brass cap set in 1944.
22" Cedar S.43°W., 8.6 ft. Tree dead. Old face showing, but scribing burned off. Rescribe dead Cedar "T25S R3W S19 CS BT".
No other bearing trees found.

(Cont Next Page)

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Blaze and scribe:

16" Red Cedar N.8½°E., 150.5 ft. mkd. "T25S R3W
S17 CS BT".

No other trees available.

Corner lies approx. 30 ft. north of Slide Creek Road and 50
ft. south of creek.

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage
July 1966 - C.S. File 54/27-4

Found - 1944 GLO brass cap mkd.
22" Cedar snag S.43°W., 8.6 ft. scribed T25S R3W
S19 CS BT.
16" Red Cedar N.8½°E., 150.5 ft. scribed & alive.
New BT - 6" Maple N.75°W., 15.2 ft. mkd. T25S R3W S18 CSBT.
Fence corner bears S.5°W., 65.3 ft., course S and W.

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J.
Flause - 1/27/98 - C.S. File 64/79-12

Found - 2½" dia., brass cap on a 2" O.D. iron pipe
protrudes 4" above ground, lean 12" North. 1944
20" now rotted remains of a Cedar, no scribing or
blazes visible, bears S.43°W., 8.6 ft.
(Agrees with rec.) 1944
16" now 26" dia., R.Cedar with a partially healed
blaze, illegible scribing visible, bears
N.8½°E., 150.5 ft. (Agrees with rec.) 1962
Plumb position of leaning fence corner, bears
S.1°W., 65.3 ft. (Rec. S.5°W., 65.3 ft.) 1966
New BTs - 11" dia., Maple, double blazed and scribed "T25S
R3W S17 CS BT" bears N.73½°E., 16.0 ft.
18" dia., D.Fir, double blazed and scribed "T25S
R3W S20 CS BT" bears S.70½°E., 41.7 ft.
15" dia., D.Fir, double blazed and scribed "T25S
R3W S19 CS BT" bears S.4½°W., 56.6 ft.
BC/IP plumbed now protrudes 6" above ground.
See sketch in file

Fd. BC & 4 BTs by Ken Hoffine, 3/2011 - M162-21