

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION ¼ Sec Cor for 32; & 5 of T.26-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which bearing tree mkd. by Bruce R. Rogers, Deputy County Surveyor, in 1965
A W.Oak 10" dia., bears N.44½°W., 45 lks., with healed blaze.
and a new bearing tree
A Ponderosa Pine 15" dia., bears S.85°E., 15 lks., mkd. ¼ S5 BT.
Corner is located on SW. slope.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike
- 11/6/2007 - C.S. File 67/24-44

Found ok as per BLM renewal of 1987-1988

Douglas Co. Surveyors Office - Crew: Jeff Lorsung- 11/26/2024
- C.S. File 67/59-17

Found - GLO brass cap (properly mkd) in mound of stone.
15" rotted Fir stump N.83½°E., 15.8 ft.
13" rotted fir stump S.22½°E., 12.5 ft.
12" w.Oak N.44½°W., 29.7 ft. (rec. 45 lks)
20" Ponderosa Pine, S.85°E., 9.9 ft. (rec. 15 lks)
New tags, spikes, no flagging due to cattle.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 186447.456 E 231405.342