

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3714)

Set Cedar post, 3 ft. long 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which
A Fir 30" dia., bears S.30°W., 23 lks., mkd. 1/4 S BT.
A Cedar 36" dia., bears N.21°W., 32 lks., mkd. 1/4 S BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11590)

The original 1/4 sec. cor. a decayed fir limb, 3 ft. long, 3" square on which only ax marks remain.
At point for corner, Set an iron post 3 ft. long, 1" dia., 28" in the ground, with decayed stake deposited at the base, for 1/4 sec. cor. with brass cap mkd. $\frac{S29}{S32}$

1943 from which
An I.Cedar 40" dia., bears N.32½°W., 11 lks., on which I uncovered the scribe marks B T beneath 60 years overgrowth. (Old BT)
A Fir 42" dia., bears S.32½°W., 11 lks., on bark 1/4 S BT. I reblaze and remark this old BT, 1/4 S32 BT.
An I.Cedar 36" dia., bears N.68¼°E., 49 lks., mkd. 1/4 S29 BT. (New BT)

Doug. County Surveyors Office - Vernon Tracy; Joe Brady; Jack Heritage - June/July 1966 - C.S. File 54/27-13

Found - 1943 GL0 brass cap mkd.
Orig. 42" Fir, now turned out, lying nearly face down S.32½°W., 7.3 ft.
1943 resurvey BT, 36" now 42" I.Cedar N.68¼°E., 32.3 ft., alive, top broken out, shows scribe on unhealed blaze.
New BTs - 12" W.Fir N.81½°E., 47.8 ft. mkd. 1/4 S29 BT.
No trees available in Sec. 32 due to logging.
Corner lies in middle of logged off area approx. 100 ft. east of logging road, course NW and SE.

BLM Dependent Resurvey - Rogers, etal, Group #1386, Survey July 1987/Sept. 1988 (DCSO records, Volume 48 Page 18488)

The 1/4 sec. cor. of sec. 29 and 32, monumented with an iron post, 1" dia., firmly set, projecting 17" above ground, with a 1943 brass cap mkd. continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

from which the remains of an original bearing tree
A root hole bears S.32½°W., 11 lks. dist., with a down
Fir alongside, 42" dia., with healed blaze.
and a bearing tree mkd. by Price
A Cedar 42" dia., bears N.68¼°E., 49 lks. dist., with
fragmentary scribe marks visible on partially
healed blaze.
and the remains of a bearing tree mkd. by Tracy, Deputy Co.
Surveyor, in 1966
A root hole, bears N.80°E., 73 lks. dist., with a down
Fir alongside, size indeterminate, with scribe marks
¼ S29 BT visible on blaze.
and a new bearing tree
A Fir 9" dia., bears S.6½°W., 15 lks. dist., mkd. ¼ S32 BT

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff
Lorsung- 7/18/2022 - C.S. File 67/54-10

Found - 1943 2½" Brass cap on iron pipe, straighten to plumb
proj. 7" in rough mound of stone.
Burnt-still alive, 52" cedar N.68¼°E., 31.5 ft.
(rec. 49 lks) add 3½" P.K. right side center,
fully healed blaze. (Price BT)
Burnt-dead 16" D.Fir S.6½°W., 10.0 ft. (rec. 15 lks)
add 3½" PK right side center. BLM 1987-88 BT
New - A 20" D.Fir burnt-dead N.13°E., 16.0 ft., 3½" PK
right side center.
A 15" burnt-dead D.Fir S.60°E., 16.9 ft. 3½" PK
right side center.
Note - Area burnt 9/2020
O CRS State Plane Coordinates - Cottage Grove - Canyonville
Zone N 192500.263 E 231689.972