

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3723)

Set Cedar post, 3" sq., 3 ft. long, 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which
A Fir 20" dia., bears S.32°W., 43 lks., mkd. 1/4 S BT.
A Fir 18" dia., bears N.41°W., 28 lks., mkd. 1/4 S BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11599)

Proportional measurement. Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor. with brass cap mkd.

1/4 S8
 S17
 1944

from which
A W.Fir 20" dia., bears N.3°E., 23 lks. mkd. 1/4 S 8 BT.
A W.Fir 20" dia., bears S.25°E., 45 lks. mkd. 1/4 S 17 BT.

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage August 1966 - C.S. File 54/27-44

Found - GLO brass cap mkd. 1944, with steel fence post alongside.
20" now 30" W.Fir N.3°E., 15.2 ft. Alive, shows good scar. We do not open.
20" now 25" W.Fir S.25°E., 29.7 ft., now snag, shows good scar.
New BTs - 18" Yew S.25°W., 26.4 ft. mkd. 1/4 S17 CS BT.
12" R.Cedar N.12°E., 18.3 ft. mkd. 1/4 S 8 CS BT.
Corner lies on gentle NE slope.

Found OK by D. Edwards, Jan. 2001 - M136-33