

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Pages 3705-06)

Set Cedar post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face, from which
A Cedar 8" dia., bears S.50°E., 10 lks., mkd. 1/4 S BT.
A Cedar 10" dia., bears S.31°W., 13 lks., mkd. 1/4 S BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11580)

Proportional measurement. Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap mkd.
1/4
S20|S21
1943 from which
A Fir 64" dia., bears S.75 1/2°E., 57 lks. mkd. 1/4 S21 BT.
A Fir 40" dia., bears N.53°W., 121 lks. mkd. 1/4 S20 BT.

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage August 1966 - C.S. File 54/27-48

Found - GL0 brass cap mkd. in 1943, bent over and steel fence post alongside.
Reset - Brass cap in proper position in mound of stone.
Found - 64" Fir, now stump, S.75 1/2°E., 37.6 ft., shows "1/4 S21 BT" scribe on unhealed blaze.
Stump of possible BT to NW, cut too low for scribe.
New BTs - 5" D.Fir S.63°W., 48.8 ft. mkd. "1/4 S20 CS BT".
5" D.Fir S.85°E., 28.6 ft. mkd. "1/4 S21 CS BT".

David Edwards - For: Roseburg Resources - 7/2002 - M 140-45

Found - GL0 brass cap
26" Fir S.63°W., 48.8 ft.
21" Fir S.85°E., 28.6 ft.
New BTs - 9" Fir N.46°E., 19.6 ft., fir scribed "1/4 S21 BT"
10" Hemlock N.30°W., 30.3 ft., hemlock scribed "1/4 S20 BT"

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 12/5/2024 - C.S. File 67/59-24

Found - 2 1/2" GL0 brass cap (properly mkd) proj 15" in rough mound of stone leans N.50°W., 0.3 ft.
continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION 1/4 Secs. 20 & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Burnt, sawn, rotted, 19"x 7 ft. D.Fir stump, S.63°W., 48.8 ft., add 3½" mag nail left side center fully healed single blaze.

Burnt, broken, rotted 16"x 4½ ft. D.Fir stub S.85°E., 28.2 ft. (rec. 28.6 ft) fully healed single blaze, add 3½" mag nail right side center.

Burned, broken 9"x5 ft. D.Fir snag, N.40°E., 19.6 ft. (rec N.46°E.) open blaze good scribes.

Broken, burnt, sawn 8"x2 ft. stub N.30°w., 30.3 ft. blaze and face gone.

Re-set red & white steel fence post 2.0 ft. North.

Note - Mon near bottom of west slope at edge of swampy bench in burned stand of older reprod.

Area burnt 9/2020
Compass decl. 14¼°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 201663.284 E 234166.840