

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 & 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3708)

Set Cedar post, 4" sq., 4 ft. long, 24" in the ground for sec. cor. to secs. 8, 9, 16 and 17, mkd. T25S S9 on NE., R3W S16 on SE., S17 on SW. and S8 on NW. faces with 4 notches on S. and 4 notches on E. edges, from which

- A Maple 8" dia., bears N.41°E., 23 lks. dist., mkd. T25S R3W S9 BT.
- A Fir 10" dia., bears S.59°E., 33 lks. dist., mkd. T25S R3W S16 BT.
- A Fir 6" dia., bears N.70°W., 26 lks. dist., mkd. T25S R3W S8 BT.
- A Maple 6" dia., bears S.55°W., 32 lks. dist., mkd. T25S R3W S17 BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11583)

Point for original cor. of secs. 8, 9, 16 and 17, determined by reference to the record measurements from the old SE. and SW. bearing trees. At point for corner, Set an iron post, 3 ft. long 2" dia., 28" in the ground, for cor. of secs. 8, 9, 16 and 17, with brass cap mkd.

T25S R3W	
<u>S8 S9</u>	
S17	S16

1944

from which

- A Fir 30" dia., bears S.65°E., 33 lks. dist., with old blaze healed. (Old BT)
- A Maple 14" dia., bears S.31°W., 32 lks. dist., with no inscription remaining on decayed face of old blaze. (Old BT)
- A R.Cedar 12" dia., bears N.50°E., 86 lks. dist., mkd. T25S R3W S9 BT. (New BT)
- A Fir 10" dia., bears S.60°W., 102 lks., dist., mkd. T25S R3W S17 BT. (New BT)
- A R.Cedar 6" dia., bears N.29°W., 50 lks. dist., mkd. T25S R3W S8 BT. (New BT)

This cor. is located in head of a shallow ravine, course NE.

continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec. Cor. 8, 9, 16 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Doug. County Surveyors Office - Vernon Tracy; Joe Brady; Jack Heritage - Aug. 1966 - C.S. File 54/27-70

Found - GLO brass cap mkd. 1944, with steel fence post set alongside.
Orig. 30" now 36" Fir S.65°E., 21.8 ft. Alive, shows old scar. Do not open.
12" now 21" R.Cedar N.50°E., 56.9 ft. shows scribe on partially healed blaze.
10" now 14" Fir S.60°W., 67.3 ft. shows good scar. Do not open.
6" now 11" Red Cedar N.29°W., 33.0 ft. healed blaze. Do not open, roots wrapped around old log.
New BTs - 26" R.Cedar S.56°E., 22.0 ft. mkd. T25S R3W S16 CS BT.
9" Hemlock N.37°W., 16.1 ft. mkd. T25S R3W S8 CS BT.
Corner lies on bench between small spurs.

Found brass cap and seven BTs.
BLM Dependent Resurvey by Rogers, etal - Group #1386 - Survey July 1987/Sept. 1988 (DCSO records, Volume 48 Pages 18484-85)

Found OK by D. Edwards, Jan. 2001 - M136-33