

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

BLM Dependent Resurvey by Rogers, Bedell; and Peterson, Group #1386 - Survey June 1987-Sept. 1988 (DCSO records Volume 48 Page 18493)

Found - Iron post 1" dia., firmly set, projecting 16" above ground with brass cap mkd: $\frac{1}{4}$ $\frac{S\ 4}{S\ 9}$
1944

from which the remains of bearing trees mkd. by Arthur Boyer, in 1940:

A Cedar snag, 11" dia. bears N.40°E., 6 lks. dist., with scribe marks $\frac{1}{4}$ S4 T25S R3W CS BT visible on open, double blaze.

A Cedar snag 9" dia. bears S.82°W., 11 lks. dist. with scribe marks $\frac{1}{4}$ S9 T25S R3W CSBT visible on open, double blaze.

and the remains of bearing trees mkd. by Vernon Tracy, deputy, in 1966:

A Grand Fir 20" dia. bears S.21½°E., 76 lks. dist. with healed double blaze.

A Cedar snag 12" dia. bears N.25°W., 12 lks. dist. with scribe marks $\frac{1}{4}$ S4 CS BT visible on open blaze.

and a new BT:

A Fir 4" dia. bears N.41¾°E., 71 lks. mkd. $\frac{1}{4}$ S4 BT.

Douglas Co. Surveyor's Office - Crew: Stephen Flause & Mike Koch - 7/7/2016 - C.S. File 67/44-18

Found - A 1" iron post by Price, in 1944, firmly set, projecting 14" above the ground with a 2½" dia. brass cap (properly) marked

BTs by Boyer, in 1940 per C.S. 35/38 & Vol. 4, PG. 80 -

A 16" dia. R.Cedar bears N.40°E., 4.5 ft. with scribe marks " $\frac{1}{4}$ S4 T25S R3W CS BT" visible on an 11" dia. dead trunk now being overgrown by the 16" tree. (Rec. 4.0 ft. Matches to the face)

A 16" dia. R.Cedar bears S.71°W., 7.3 ft. with scribe marks " $\frac{1}{4}$ S9 T25S R3W CS BT" visible on a 9" dia. Dead trunk now being overgrown by the 16" tree. (1987 USBLM Rec. S.82°W., 7.3 ft.)

And BTs by Tracy in 1966 PER C.S.54/27-69 -

A 17" dia. R.Cedar bears N.25°W., 7.8 ft. with illegible scribe marks visible on a 10" dia. Dead and rotted cedar trunk now being overgrown by the 17" tree. (1987 USBLM Rec. 7.3 ft.)

A 25" dia. x 25' tall W.Fir snag bears S.22°E., 50.3 ft. with a healed double blaze.

continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

And a BT by Rogers, Bedell & Peterson, in 1987 -
A 15" dia. x 8' tall sawn fir stump bears N.40°E.,
46.5 ft. with a healed single blaze. (Rec.
N.41¾°E., 46.9 FT.)
New BT - A 12" dia. D.Fir bears S.25½°W., 32.5 ft. scribed
"¼ S9 CS BT".
Location & comments - All BTs have BT tags attached. All new
BTs have double blazed faces with bearings
measured to the center of the tree at the root
crown and distances measured to the side and
center of the root crown.
The corner falls on relatively flat ground in a
small remaining stand of young fir and cedar
timber on the westerly edge of a large clear cut
unit approximately 30' SW of USBLM RD #24-3-31.
(See vicinity sketch in attached notes)
Compass declination 15°E.

Douglas Co. Surveyor's Office - Crew: Stephen Flause & Jeff
Lorsung - 6/15/2021 - C.S. File 67/49-14

Found - 1" iron pipe with 2½" brass cap projecting 14" above
ground.
16" burnt cedar stub N.40°E., 4.5 ft.
Burnt 17"x2' cedar stump N.25°W., 7.8 ft.
Root hole S.22°E., 50.3 ft.
Burnt shattered Fir stump N.40°E., 46.5 ft.
13" uprooted fir S.25½°W., 32.5 ft., burnt blaze to
root hole.
New - 28"x3' burnt fir stump S.71°E., 92.6 ft., nail &
washer top center.
8"x3' burnt R.Cedar stump S.11°E., 51.7 ft., nail &
washer top center.
24"x3' burnt R.Cedar stump S.86°W., 12.3 ft., nail
& washer top center.
14" D.Fir N.27½°W., 75.0 ft., brass washer & mag
nail in face.
Note - Corner is approx. 30' SW of BLM road 24-3-31
Area badly burnt 9/2020
Compass decl. 14¾°E.
Lat: 43°25'23.46" N
Long: 123°03'31.02" W