

PRIMARY CORNER DESCRIPTION 1/4 Corner for Secs. 27 and 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3693)

Set Cedar post 3 ft. long 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face, from which
A Fir 20" dia., bears N.11°W., 38 lks., mkd. 1/4 S BT.
A Cedar 30" dia., bears S.71°E., 13 lks. mkd. 1/4 S BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11565)

Proportional measurement. Set an iron post, 3 ft. long, 1" dia., 20" in the ground to bedrock, and in a mound of stone to top, for 1/4 sec. cor., with brass cap mkd. 1/4
S28|S27
1943

from which
A Fir 48" dia., bears S.42°E., 64 lks., mkd. 1/4 S27 BT.
A Fir 42" dia., bears S.44°W., 59 lks., mkd. 1/4 S28 BT.

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage July 1966 - C.S. File 54/27-26

Found - 1943 GLO brass cap mkd.
48" Fir, now stump & turned out, S.42°E., 42.2 ft. no scribe found.
42" now 46" Fir, now stump S.44°W., 38.9 ft fragmentary scribe visible on partially healed blaze.

New BTs - 5" Hemlock S.33°E., 27.8 ft. mkd. 1/4 S27 CS BT.

5" Red Cedar N.86°W., 47.2 ft. mkd. 1/4 S28 CS BT.

This cor. lies approx. 200 ft. North of small creek, course East. Brass cap in middle of small blowdown Hemlock.

BLM Dependent resurvey by A. Bert Skeesick & Kenneth W. Saveland, Cadastral Surveyors and Robert H. Browning, Survey Tech, under Group No. 2212 surveyed July/Oct. 2008 - (DCSO records Vol. 57 Page(s) 22438)

The 1/4 sec. cor. of secs. 27 and 28, perpetuated by the Douglas County Surveyor's Office in 1966, monumented with an iron post, 1" dia., firmly set, projecting 5" above a collar of stone, with brass cap (properly) mkd.

from which the remains of a bearing tree mkd. by Price

A sawed fir stump, 47" dia., bears S.44°W., 38.9 ft., with no marks visible. continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

and the BTs mkd. by the Douglas County Surveyor's Office
A hemlock, 16" dia., bears S.34 $\frac{3}{4}$ °E., 28.0 ft., with a
healed blaze.
A cedar, 15" dia., bears N.86 $\frac{1}{4}$ °W., 46.3 ft., with a healed
blaze.

Ron Quimby - For: Roseburg Resources - March 2015 - M166-32

Found - 1943 GLO brass cap
18" Hemlock S.35°E., 28.0' healed scar
47" sawed fir stump S.44°W., 38.9' no visible scar
16" cedar N.86°W., 46.3' healed scar
New BT - 11" Fir N.31°E., 19.1' scribed " $\frac{1}{4}$ S27 BT"