

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3697)

Set Hemlock post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. mkd. 1/4 S on W. face, from which
A Fir 36" dia., bears N.10°E., 16 lks. dist., mkd. 1/4 S BT.
A Fir 6" dia., bears S.35°W., 9 lks. dist., mkd. 1/4 S BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11570)

Point for original 1/4 se.cor., determined by reference to the record measurements from both original bearing trees. At point for corner, set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap mkd.

1/4
S16|S15
1943 from which
A sawed Fir stump 40" dia., bears N56°E., 16 lks. dist., on which no marks remain. (Old BT)
A Hemlock stub 5" dia., bears N.59°W., 9 lks. dist., mkd. 1/4 S BT. (Old BT)
A Fir 30" dia., bears N.60°E., 48 lks. dist., mkd. 1/4 S 15 BT. (New BT)
A Red Cedar 28" dia., bears N.25 1/4°W., 67 lks. dist., mkd. 1/4 S16 BT. (New BT)

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage Aug/Sept. 1966 - C.S. File 54/27-67

Found - GL0 brass cap mkd. in 1943 with steel fence post alongside.
Scribe marks "1/4 S15 BT" found on 1943 BT to NE, now shattered snag.
Other BTs destroyed by logging.
New BTs - 5" D.Fir S.82°E., 23.8 ft. mkd. 1/4 S15 CS BT.
7" D.Fir N.53°E., 19.9 ft. mkd. 1/4 S15 CS BT.
6" D.Fir N.55°W., 8.1 ft. mkd. 1/4 S16 CS BT.
This corner lies in very dense reproduction of D.Fir, Hemlock, Cedar.

continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 9/14/2022 - C.S. File 67/55-2

Found - 2½" brass cap on 1/2" I.D. iron pipe, up 13".
Roothole S.82°E., 23.8 ft. 1966
Sawn 17"x7½ ft., D.Fir stump N.53°E., 20.5 ft. (Rec. 19.9 ft) 3½" mag nail right side center. 1966
Sawn 9"x6 ft., D.Fir stump N.55°W., 8.1 ft., 3½" mag nail right side center.

New - Sawn Fir stump 21"x9 ft. N.4°E., 18.7 ft., 3½" mag nail right side center.
Sawn Fir stump 10"x6 ft. S.87°W., 6.5 ft., 3½" mag nail right side center.

Note - Area burnt 9/2020
Compass decl. 14½°E.
For sketch see sheet (in file)

OCRS Coordinate system
Cottage Grove - Canyonville Zone NAD 88
N 207081.107
E 240167.029