

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3697)

Set Yew post, 4 ft. long, 4" sq., 24" in the ground for corner to secs. 9, 10, 15 and 16, mkd. T25S S10 on NE., R3W S15 on SE., S16 on SW., and S9 on NW., faces, with 4 notches on S. and 3 notches on E. edges, from which

- A Fir 24" dia., bears N.20°E., 7 lks. dist., mkd. T25S R3W S10 BT.
- A Hemlock 12" dia., bears S.10°E., 50 lks. dist., mkd. T25S R3W S15 BT.
- A Fir 30" dia., bears S.21°W., 33 lks. dist., mkd. T25S R3W S16 BT.
- A Fir 40" dia., bears N.44°W., 48 lks. dist., mkd. T25S R3W S9 BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11571)

Point for original cor. determined at the mean position of the record measurements from the old SE., SW., and NW. BTs. At point for corner, Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor., with brass cap marked:

T25S R3W	
S9	S10
S16	S15

1943

from which

- A dead fir, 20" dia., bears S.21°E., 52 lks. dist., mkd. on bark T25S R3W S15 BT. (Old BT)
- A sawed Fir stump 50" dia., bears S.50°W., 33 lks. dist., on which no marks remain. (Old BT)
- A sawed Fir stump 40" dia., bears N.61½°W., 50 lks. dist., on which no marks remain. (Old BT)
- A Fir 44" dia., bears N.3¼°E., 46 lks. dist., mkd. T25S R3W S10 BT. (New BT)
- A Hemlock 14" dia., bears S.88¼°E., 10 lks. dist., mkd. T25S R3W S15 BT. (New BT)
- A Fir 12" dia., bears S.83¼°W., 117 lks. dist., mkd. T25S R3W S16 BT. (New BT)
- A Red Cedar 22" dia., bears N.8°W., 97 lks. dist., mkd. T25S R3W S9 BT. (New BT)

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Doug. County Surveyors Office - Vernon Tracy; Joe Brady;
Jack Heritage - July/Aug. 1966 - C.S. File 54/27-51

Found - GLO brass cap mkd. 1943, with steel fence post
 alongside.
 14" now 20" Hemlock S.88¼°E., 6.6 ft. shows partial
 scribe on nearly healed blaze.
 All other BTs destroyed by logging, now stumps,
 turnouts, etc.
New BTs - 12" Hemlock S.75°W., 60.7 ft. mkd. T25S R3W S16 CSBT
 6" Hemlock N.56°W., 33.5 ft. mkd. S 9 CS BT.
 6" D.Fir N.41°E., 48.6 ft. mkd. S 10 CS BT.
Corner lies approx. 375 ft. E. of creek, course N. on flat
bench.