

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Leban H. Wheeler, under Contract #467 dated April 7, 1883 (DCSO records, Volume 9 Page 3699)

-----  
Set Yew post, 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 3, 4, 9 and 10, mkd. T 25 S S 3 on NE., R 3 W S 10 on SE., S 9 on SW., and S 4 on NW. faces, with 5 notches on S. and 3 notches on East edges, from which  
A Cedar 5" dia. bears N.55°E., 4 lks. dist. mkd. T25S R3W S3 BT.  
A Cedar 6" dia. bears S.31°E., 8 lks. dist. mkd. T25S R3W S10 BT.  
A Cedar 4" dia. bears S.69°W., 8 lks. dist. mkd. T25S R3W S9 BT.  
A Cedar 6" dia. bears N.41°W., 11 lks. dist. marked T25S R3W S4 BT.

A. Boyer, Deputy Co. Surveyor - Wit: Ted Shellabarger; Joe Murphy - April 1940 - C.S. File 35/38; Vol. 4 Page 80

-----  
Set cor. from 60" Fir scribed by Oscar Edwards. (M 6-24)  
Drove a 4" x 4" Fir post from which I set new trees:  
A Maple 6" bears S.41°E., 23.0 ft.  
A Fir 6" bears S.60°W., 23.6 ft.  
A Fir 5" bears N.45°W., 3.0 ft.

Bureau of Land Management Dependent Resurvey by Norman D. Price under Special Instructions dated April 5, 1940 (Survey 1943) (DCSO records, Volume 27 Page 11573)

-----  
The original cor. of secs. 3, 4, 9, and 10, the locus of which has been perpetuated by the county surveyor's Hemlock stake, 3 ft. long 4" square, firmly set, mkd. S 3 on NE., S 10 CS on SE., S 9 on SW., and S 4 CS on NW. face.  
At point for corner, set an iron post 3 ft. long 2" dia. 28" in the ground, with the county surveyor's marked stake deposited at the base, for cor. with brass cap marked:

T25S R3W  
S4|S3  
-----  
S9|S10  
1943 from which  
A Cedar stump 50" dia. bears N.55°E., 5 lks. dist. on which only ax marks remain. (Old BT)  
A Fir 62" dia. bears N.35°E., 39 lks. dist., mkd. on bark T25S R3W S3 CS BT. I re-blaze and re-mark this county surveyor's BT, T25S R3W S3 BT.  
A Maple 7" dia. bears S.41½°E., 35 lks. dist. mkd. S10 T25S R3W W C S BT. (A Co. Surveyors tree) cont.

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. 3, 4, 9, & 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 8" dia. bears S.58½°W., 36 lks. dist., mkd. S9  
T25S R3W W C S BT. (A Co. Surveyors tree)  
A Hemlock 6" dia. bears N.51°W., 5 lks. dist. marked  
S4 T25S R3W W C S BT. (A Co. Surveyors tree)  
A Fir 20" dia. bears S.10 3/4°E., 131 lks. dist. mkd.  
T25S R3W S10 BT. (New BT)

Doug. Co. Surveyors Office - Vernon Ray Tracy; Jack Heritage;  
Joe Brady - July & Aug. 1966 - C.S. File 54/27-52  
-----  
Found - GLO brass cap mkd. in 1943, with steel fence post  
alongside, and following BTS:  
8" now 13" D.Fir S.58½°W., 23.8 ft. shows good scar,  
do not open  
6" now 12" Hemlock N.51°W., 3.3 ft., shows good  
scar. Do not open.  
Maple to SE down. 20" Fir to SE gone.  
Cedar stump to NE very badly burned. 62" Fir to NE  
now stump.  
New BTs- 9" D.Fir N.81°E., 18.4 ft. mkd. T25S R3W S3 CS BT.  
11" D.Fir S.18°E., 31.3 ft. mkd. T25S R3W S10 CS BT.  
Corner lies on gentle NE slope on bench.

DCSO Fd. ok, tags re-nailed and trees flagged - S.J. Flause  
& M.S. Koch - 7/18/2016 - C.S. File 67/44-23