

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 34; & 3 of T26-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855
(DCSO Records, Volume 9 Page 3663)

Set Qr. sec. post, from which
A Cedar 4" dia., bears S.10°E., 2 lks. dist.
A Hemlock 3" dia., bears N.46°E., 18 lks. dist.

GLO Dependent Resurvey by Norman D. Price, Under Special
Instructions dated April 5, 1940 (DCSO records, Volume 27
Page 11505)

The original ¼ sec. cor., a badly decayed cedar stake, 36"
long, 4" square, firmly set, on which no marks remain.
At point for corner, Set an iron post, 3 ft. long, 1" dia.,
28" in the ground, with the decayed stake deposited at the
base, for ¼ sec. cor., with brass cap mkd. ¼ S34
S3
1943

from which
A Hemlock stub, 6" dia., bears N.54¼°E., 22 lks. dist.,
mkd. ¼ S BT. (Old BT)
A Red Cedar 16" dia., bears S.17°W., 4 lks. dist., with
old blaze healed. Old BT)
A Fir 54" dia., bears N.15°W., 23 lks. dist., mkd. ¼ S 34
BT. (New BT)
A Yew 5" dia. bears S.88°E. 22 lks., mkd ¼ S 3 BT (New BT)

Doug. County Surveyors Office - Vernon Tracy; Mike Stone;
Jack Heritage - February 1966 - C.S. File 54/7-41

Found - 1942 GLO brass cap mkd. & BTs as follows:
Orig. 16" R.Cedar S.17°W., 2.6 ft. shows old scar.
Do not open.
54" now 56" D.Fir N.15°W., 15.2 ft. shows good scar.
Do not open.
5" now 6" Yew stump S.88°E., 14.5 ft. shows "¼ S3BT"
unhealed face.
New BTs- 6" yew N.10°E., 25.1 ft. mkd. ¼ S34 CS BT.
16" R.Cedar S.6°E., 31.4 ft. mkd. ¼ S3 CS BT.
This corner lies 24 ft. East of small creek, course SE.

Doug. County Surveyors Office - L.E. Monrean; P.L. Earle
Sept. 20, 1976 - C.S. File 59/24-4

Found - 1943 GLO brass cap properly stamped.
4" now 17" Red Cedar bears S.17°W., 2.6 ft. Tree has
well healed blaze. I do not open.
continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 440100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 34; & 3 of T26-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

54" now 56" Fir stump, bears N.15°W., 15.2 ft. Stump has a well healed blaze. I do not open.
A 5" yew now a 6" staub, bears S.86°E., 14.3 ft. (Rec. S.88°E., 14.5 ft., has been hit by log. Stump is very loose) Stump scribed "¼ S3 BT".
Original 6" Hemlock in NE Quad. now gone.
6" Yew bearing N.10°E., 25.1 ft. has been pushed over by cat logging.
16" Red Cedar now 18" bears S.6°E., 31.4 ft. Tree double blazed and scribed "¼ S3 CS BT."
New BT - 15" Red Cedar, bears N.79½°E., 23.8 ft. Tree double blazed. Scribed "¼ S34 CS BT".

Fd. Ok - Herman Pieske - Jan. 21, 1994 - M118-33

Fd. & used on BLM dependent resurvey by Bryan s. Seibold, Cadastral Surveyor & Robert H. Browning, Surveying Technician, under Group #1777, surveyed Aug./Sept. 1995 - (DCSO records Vol. 52 Page(s) 19888)

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 11/7/2007 - C.S. File 67/24-45: Found ok, 3 live BTs

BLM Dependent resurvey by A. Bert Skeesick & Kenneth W. Saveland, Cadastral Surveyors and Robert H. Browning, Survey Tech, under Group No. 2212 surveyed July/Oct. 2008 - (DCSO records Vol. 57 Page(s) 22441-2)

The ¼ sec. cor. of secs. 3 and 34, on the S. bdy. of the Tp., monumented with an iron post, 1" dia., firmly set, projecting 9" above ground, with brass cap (properly) mkd. from which the remaining original bearing tree
A cedar, 27" dia., bears S.17°W., 2.6 ft., with a healed blaze.
and the remains of a bearing tree mkd. by Price
A sawed fir stump, 52" dia., bears N.15°W., 15.2 ft., with axe marks visible.
and a bearing tree mkd. by the Douglas County Surveyor's Office in 1966, reported by Seibold
A cedar, 23" dia., bears S.7½°E., 31.7 ft., with a healed double blaze.
and a bearing tree mkd. by the Douglas County Surveyor's Office, in 1976, reported by Seibold
A cedar, 26" dia., bears N.77°E., 23.8 ft., with a healed double blaze.
Corner is located on a SW. slope, E., 25 ft. from a creek, 3 ft. wide, course S.35°E.