

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3693)

Set Yew post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor., mkd. 1/4 S on N. face, from which
A Dogwood 7" dia., bears N.31°W., 43 lks. mkd. 1/4 S BT.
A Fir 12" dia., bears S.19°W., 34 lks., mkd. 1/4 S BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11565)

Proportional measurement. Set an iron post, 3 ft. long, 1" dia., 28" in the ground for 1/4 sec. cor. with brass cap mkd.
1/4 $\frac{S27}{S34}$
1943 from which
A Fir 40" dia., bears N.7°E., 43 lks., mkd. 1/4 S27 BT.
A Fir 48" dia., bears S.64°E., 16 lks., mkd. 1/4 S34 BT.

Doug. County Surveyors Office - Vernon Tracy; Joe Brady; Jack Heritage - June/July 1966 - C.S File 54/27-7

Found - 1943 GL0 brass cap mkd. & 1943 BTs as follows:
40" Fir N.7°E., 28.4 ft. now dead snag, shows "1/4 S27 BT" on unhealed blaze.
48" now 50" Fir S.64°E., 10.6 ft., shows good good scar. Alive.
New BTs - 9" Hemlock N.51°E., 26.4 ft. mkd. 1/4 S27 CS BT.
7" Hemlock S.29°E., 9.9 ft. mkd. 1/4 S34 CS BT.
This cor. lies at SE corner of cutoff unit in Sec. 27, approx. 1000 ft. east of Kelley Creek Road.

BLM Dependent resurvey by A. Bert Skeesick & Kenneth W. Saveland, Cadastral Surveyors and Robert H. Browning, Survey Tech, under Group No. 2212 surveyed July/Oct. 2008 - (DCSO records Vol. 57 Page(s) 22437-8)

The 1/4 sec. cor. of secs. 27 and 34, perpetuated by the Douglas County Surveyor's Office in 1966, monumented with an iron post, 1" dia., firmly set, projecting 2" above ground, with brass cap (properly) mkd.
from which the remains of bearing trees mkd. by Price
A fir snag, 37" dia., bears N.7°E., 28.4 ft., with a hollow blaze.
A sawed fir stump, 36" dia., bears S.64°E., 10.6 ft., with a healed blaze. continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

and the remains of bearing trees mkd. by the Douglas County Surveyor's Office
A decayed hemlock snag, 12" dia., bears N.51°E., 26.6 ft., with fragmentary scribe marks visible on a partially healed blaze.
A hemlock, 20" dia., bears S.29°E., 10.2 ft., with a healed blaze.
and a new bearing tree
A fir, 9" dia., bears N.56½°E., 10.2 ft., mkd. ¼ S27 BT.
Corner is located on a broken E. slope.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 6/6/2023 - C.S. File 67/56-27

Found - GLO brass cap (properly mkd) up 2"
Very burned 30"x12 ft Fir snag N.7°E., 28.4 ft, add 3½" mag nail right side center.
Burned, rotted, 34"x4½ ft. fir stump S.64°E., 10.6 ft.
Burned, sawn, 24"x2½ ft. Hemlock stump S.29°E., 10.0 ft. (rec. 10.2 ft.) portion of fully healed blaze, add 3½" mag nail top center.
Burned, dead, 10" Fir N.56½°E., 10.2 ft. add 3" mag nail right side center.
New - Burned, dead, 24" Hemlock N.22½°E., 29.6 ft., 3½" mag nail right side center not blazed or scribed.
Burned, sawn, 20"x2½ ft. Fir stump S.60°W., 18.0 ft. 3½" mag nail top center
Note - Area burnt 9/2020
Compass decl. 14½°E.
Corner on moderate East slope, clear cut to south, burned forest north. Monument is approx 200' NE'ly from end of dirt road.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 191756.370 E 242045.904