



TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 334 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

with an iron post, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass cap (properly) mkd. from which the remains of an original bearing tree

A decayed cedar stump, size indeterminate, bears N.62°E., 14.5 ft., with axe marks visible.

and the remains of bearing trees mkd. by Price

A decayed fir snag, 12" dia., bears S.35°E., 3.3 ft., with scribe mark 3 and other fragmentary scribe marks visible on a partially healed blaze.

A fir, 42" dia., bears S.88°W., 23.8 ft., with a healed double blaze.

and a BT mkd. by the Douglas County Surveyor's Office

A fir, 23" dia., bears S.54½°E., 31.8 ft., with a healed blaze.

Corner is located on a broken E. slope.