

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3682)

Set Hemlock post, 3 ft. long, 3" sq., 24" in the ground for $\frac{1}{4}$ sec. cor. mkd. $\frac{1}{4}$ S on W. face, from which
A Hemlock 12" dia., bears S.85°E., 68 lks. mkd. $\frac{1}{4}$ S BT.
A Hemlock 15" dia., bears N.70°W., 56 lks. mkd. $\frac{1}{4}$ S BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11555)

Point for original $\frac{1}{4}$ sec. cor. determined at the record bearing and distance from the original SE bearing tree. At point for corner, set an iron post, 3 ft. long, 1" dia., 28" in the ground for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$\frac{1}{4}$
S27|S26
1943 from which
A Hemlock 20" dia., bears S.85°E., 68 lks. on which I uncovered the scribe marks BT beneath 60 years overgrowth. (Old BT)
A Fir 50" dia., bears South, 54 lks., mkd. $\frac{1}{4}$ S26 BT. (New BT)
A Fir 50" dia., bears S.60 $\frac{1}{2}$ °W., 159 lks., mkd. $\frac{1}{4}$ S27 BT. (New BT)

Doug. County Surveyors Office - Vernon Tracy; Joe Brady; Jack Heritage - June 1966 - C.S. File 54/27-10

Found - 1943 GLO brass cap mkd.
50" now 53" Fir south 35.6 ft., shows good scar. Alive.
50" now 55" Fir S.60 $\frac{1}{2}$ °W., 104.9 ft., shows good scar. Alive.
Orig. 1883 Hemlock S.85°E., 44.9 ft., now shattered stump, no scribe found.
New BT - 9" Hemlock S.54°W., 27.9 ft. mkd. $\frac{1}{4}$ S27 CS BT.
10" R.Cedar N.48°E., 32.5 ft. mkd. $\frac{1}{4}$ S26 CS BT.
Section line is well blazed N. and S.

Fd. OK, Nick Juliano, Dec. 1976, C.S. 58/130

continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

BLM Dependent resurvey by A. Bert Skeesick & Kenneth W. Saveland, Cadastral Surveyors and Robert H. Browning, Survey Tech, under Group No. 2212 surveyed July/Oct. 2008 - (DCSO records Vol. 57 Page(s) 22431-2)

The ¼ sec. cor. of secs. 26 and 27, perpetuated by the Douglas County Surveyor's Office in 1966, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.

from which the remains of an original bearing tree

A sawed fir stump, 53" dia., bears South, 35.6 ft., with no marks visible.

and the remains of a bearing tree mkd. by Price

A sawed fir stump, 68" dia., bears S.60½°W., 104.9 ft., with no marks visible.

and the remains of a bearing tree mkd. by the Douglas County Surveyor's Office

A hemlock stump, size indeterminate, bears S.53¾°W., 27.7 ft., with no marks visible.

and new bearing trees

A fir, 10" dia., bears S.1/4°E., 13.3 ft., mkd. ¼ S26 BT.

A fir, 9" dia., bears N.60°W., 4.8 ft., mkd. ¼ S27 BT.