

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3686)

Set Hemlock post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face, from which
A Hemlock 8" dia., bears S.61°E., 16 lks. dist., mkd. 1/4 S BT.
A Fir 24" dia., bears S.70°W., 57 lks. dist., mkd. 1/4 S BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11559)

Point for original 1/4 sec. cor., determined by reference to the record measurement from both old bearing trees. At point for corner, set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap mkd.

1/4
S15|S14
1943

from which

A dead Hemlock 18" dia., bears S.38 1/2°E., 16 lks., with blaze healed. (Old BT)
A Fir 28" dia., bears S.15 1/2°W., 57 lks., mkd. on bark 1/4 S BT. (Old BT)
A Fir 30" dia., bears N.77°E., 220 lks., mkd 1/4 S14 BT. (New BT)
A Hemlock 20" dia., bears S.60 1/2°W., 120 lks., mkd. 1/4 S15 BT. (New BT)

Doug. County Surveyors Office - Vernon Tracy; Joe Brady Jack Heritage - July/Aug. 1966 - C.S. File 54/27-59

Found - 1943 Brass cap mkd. 1/4 15|14 1943, with steel fence post alongside.

All BTs are stumps except orig. SE. Scribe found on 1943 BT to SW.

New BTs - 7" D.Fir S.37°W., 12.3 ft. mkd. 1/4 S15 CS BT.
6" D.Fir S.55°E., 15.2 ft. mkd. 1/4 S14 CS BT.

Corner lies in old logged unit now covered with very dense reproduction of D.Fir, Hemlock and Cedar.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/31/2022 - C.S. File 67/54-31

Found - 1943 GL0 brass cap on 1" iron pipe. Cont.

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 14 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

13" burnt, broken, rotted D.Fir stump 4 ft. S.27°W.,
(rec. S.37°W.) 12.3 ft. healed double blaze.
14" burnt, broken, rotted 4½' D.Fir stump S.66°E.,
(Rec. S.55°E.) 15.2 ft. healed double blaze.
Steel fence post alongside.

New - 4 - 5/8"x30" iron rods with DCS0 Yellow plastic cap
up 4"
North 5.0 ft.
S.16½°E., 67.5 ft.
S.2½°W., 53.0 ft.
West 5.0 ft.

Note - Corner is approx. 65 ft. North of gravel spur RD.
Area burnt 9/2020
Compass decl. 14½°E.
Corner is on moderate north slope.

OCRS Coordinates Cottage Grove - Canyonville Zone
N 207202.237
E 245378.030