TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3679)

Set Dogwood post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., mkd. ¼ S on W. face, from which
A Fir 8" dia., bears N.20°E., 19 lks. dist., mkd. ¼ S BT.
A Vine Maple 8" dia., bears S.32°W., 43 lks. dist., mkd. ¼ S BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11552)

Proportional measurement. Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for ¼ sec. cor., with brass cap mkd. ¼ S2|S1 1944
from which
A Cedar 36" dia., bears S.52¼°E., 21 lks. mkd. ¼ S 1 BT.
A Cedar 30" dia., bears S.51½°W., 93 lks. mkd. ¼ S 2 BT.

Douglas Co. Surveyors Office - V.R. Tracy - Aug. 22, 1966 - C.S. File 54/27-62

Looked for not found.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/19/2022 - C.S. File 67/54-26

Looked for, not found.
Used GPS ties from related corners. Fire & logging activity has obliterated al evidence.