

PRIMARY CORNER DESCRIPTION W ¼ Cor Sec. 18 only of T.25-2

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April 5, 1940 (DCSO records, Volume 27 Page 11515)

-----  
Mid-point on the W. bdy. of sec. 18. Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for ¼ sec. cor. of sec. 18 only, with brass cap mkd. ¼ S18  
1943 from which  
A Hemlock, 22" dia., bears N.77°E., 21 lks. mkd. ¼ S18 BT  
A Fir 54" dia., bears S.18½°E., 65 lks., mkd. ¼ S18 BT.

Douglas County Surveyors Office - Vernon Tracy; Joe Brady; Jack Heritage - Aug. 1966 - C.S. File 54/27-182

-----  
Found - GLO brass cap mkd. "¼ /S18 1942".  
22" now 26" Hemlock N.77°E., 13.9 ft. mkd. "¼ S18 CC BT" on unhealed blaze.  
54" now 60" Fir S.18½°E., 42.9 ft., shows good scar. Alive; we do not open.  
New BTs - 11" Hemlock S.45°E., 25.6 ft. mkd. ¼ S18 CS BT. (4 ft. off ground)  
18" Red Cedar N.60°E., 32.3 ft. mkd. ¼ S18 CS BT.  
Corner lays on SW moderate slope.

Ron Quimby - For: Roseburg Resources - Feb 2014 - M167-34 A&B

-----  
Found - GLO brass cap (properly) mkd.  
10" Fir bears N.41°W., 19.4 ft visible scar [no record]  
27" (8" tall) hemlock stump bears N.77°E., 13.7 ft visible scar.  
24" fir bears S.7°W., 15.6 ft visible scar [no record]  
23" D.Fir bears S.57°W., 15.2 ft visible scar [no record]  
62" Fir bears S.18½°E., 42.9 ft visible scar.