

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 700636

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 6 only, T25-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April 5, 1940 (DCSO records, Volume 27 Pages 11518-19)

Proportional measurement. Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor. of sec. 6 only, with brass cap marked: 1/4 S 6

1943 from which
A Hemlock 8" dia., bears N.34°E., 20 lks. dist., mkd.
1/4 S 6 BT.
A Fir 32" dia., bears S.40°E., 3 lks. dist., mkd.
1/4 S 6 BT.

Glen McChesney - For: Weyerhaeuser Co. - Dec. 1, 1959 - C.S. File 53/112-3

Found - 1943 Cadastral brass cap.
8" Hemlock, now dead, face burned, no scribing visible, bears N.34°E., 13.4 ft.
32" now 36" Fir, bark badly burned, face not opened, bears S.40°E., 1.6 ft.
Weyerhaeuser Co. July 24, 1952 visit:
42" Fir stump, S.54°W., 20.3 ft., found notch, no "W" nail or plate.
8" Hemlock, N.37°E., 12.5 ft., plate off.
36" Fir BT, S.15°E., 1.0 ft. found "W" nail, plate burned off.
Accessories added this date: (1959)
36" Fir, S.40°E., 1.0 ft. "W" nail and plate. (1943 BT)
42" Fir stump S.51°W., 20.2 ft. "W" nail and plate. (1949 BT).

David Edwards - For: Roseburg Resources Co. - July 2013 - M165-53

Found - Brass cap
36" Fir snag S.40°E., 1.0'
New - 7" dia., hemlock bears N.8°E., 5.75 ft.
9" dia., hemlock bears S.14°E., 5.9 ft.
6 ft. steel post set 2 ft. N.88°40'E.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 12/11/2023 - C.S. File 67/57-26

Found - GL0 2 1/2" brass cap (properly mkd) on 1" ID iron pipe projecting 12"
continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 700636

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 6 only, T25-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Burned, rotted 28"x20 ft Fir snag S.40°E., 1.0 ft. to head of "W" nail.
Burned, sawn 9"x1 ft Hemlock stump N.6°E., 5.75 ft. (rec. N.8°E.) evidence of blaze inside, add 3½" mag nail top center.
Burned, dead 11" Hemlock S.17°E., 5.9 ft (rec. S.14°E.) fully healed double blaze, face burned off, add 3½" mag nail right side center.
Reset 6 ft. metal post 2 ft west.

Note - Mon. is approx 150' south of logging spur rd.
Mon. is at NW cor of standing burnt timber, all other quadrants clear cut.
Compass decl. 14½°E.

Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 146408.826 E 157103.341